

New Jersey Police Crash Investigation Report												Case Number 2018-00026217			Page 2 of 3	
E F G H I J	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death		

144. Crash Diagram

Show NORTH by Arrow
(Not to Scale)

SEE ATTACHED DIAGRAM

145. Crash Description/Narrative

Investigation at the scene revealed: The driver of V2 (Vehicle 2) was traveling West on RT. 70 and was approximately 35 feet East from the intersection of RT. 70 / Olden St. The driver of V1 (Vehicle 1) was traveling directly behind V2. The accident occurred when the driver of V1 collided into the rear end of V2. On scene I observed damage to the rear end of V2 and no damage to front of V1. The driver of V1 stated she dropped her cell phone and was reaching for it when the accident occurred.

All passengers stated they were not injured and declined first aid attention. Both vehicles were removed from the roadway prior to my arrival.


146. Officer's Signature Kevin A Docherty	147. Badge # 275	148. Reviewer Robert A Hine	Badge # 158	149. Case Status ☐ Pending ☒ Complete
--	---------------------	--------------------------------	----------------	---

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram

Police Dept: Brick Police Code: 01
Station: Case No: 2018-00026217

144 Crash Diagram (NOT TO SCALE)

○ Indicate North



Kevin A Docherty

275