

New Jersey Police Crash Investigation Report												Case Number 2018-00029159			Page 2 of 3	
E F G H I J	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death		

144. Crash Diagram

Show NORTH by Arrow
(Not to Scale)

SEE ATTACHED DIAGRAM

145. Crash Description/Narrative

Vehicle 1 and 2 were both traveling eastbound on Rt 70 in the rightmost lane. Vehicle 2 began slowing due to traffic. Vehicle 1 failed to observe vehicle 2 slowing, causing it to collide with the rear of it.

The driver of vehicle 1 advised she was traveling eastbound on Rt 70 in th rightmost lane behind vehicle 2. Driver 1 further advised she observed vehicle 2 begin slowing and she applied her brakes. Driver 1 stated she skid on the wet pavement then collided with the rear of vehicle 2.

The driver of vehicle 2 advised she was traveling eastbound on Rt 70 in the rightmost lane when she began slowing due to traffic. Driver 2 further advised she was then struck in the rear forcefully by vehicle 1.


The driver of vehicle 1 is found to be at fault for the collision and has been issued a summons for Careless Driving (39:4-97) on summons T 157518. Driver 1 was also issued an additional summons for Unsafe Tires (39:3-72) on summons T157519.

146. Officer's Signature Chase S Carter	147. Badge # 280	148. Reviewer Joseph T Pacitti	Badge # 238	149. Case Status ☐ Pending ☒ Complete
--	---------------------	-----------------------------------	----------------	---

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram


Police Dept: Brick Police Code: 01
Station: Case No: 2018-00029159

144 Crash Diagram (NOT TO SCALE)



NOT TO SCALE

Route 70



Chase S Carter

Officer's Signature

280

Badge Number