

NJTR-1 (Rev. 01/17)

New Jersey Police Crash Investigation Report												Case Number 2018-00021359			Page 2 of 3	
E F G H I J	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death		

144. Crash Diagram

Show NORTH by Arrow
(Not to Scale)

SEE ATTACHED DIAGRAM

145. Crash Description/Narrative

Vehicle #2 was stopped in traffic on Route 70 west in the right lane. Vehicle #1 was behind Vehicle #2 on Route 70. Vehicle #1 failed to stop, striking Vehicle #2 from behind.

Driver #2 stated he was stopped in traffic and was struck from behind by Vehicle #1.

Driver #1 admitted he was traveling west on Route 70 and was unable to stop in time when he observed Vehicle #2 stopped in traffic. Driver #1 stated he then struck Vehicle #2 from behind.

Vehicle #1 was hauling a black 2013 trailer, NJ registration TLV 69F. The trailer is also registered to Mata GMG Construction LLC.

146. Officer's Signature Michael V Feeney	147. Badge # 200	148. Reviewer Robert A Hine	Badge # 158	149. Case Status ☐ Pending ☒ Complete
--	---------------------	--------------------------------	----------------	---

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram


Police Dept: Brick Police Code: 01

Station: Case No: 2018-00021359

144 Crash Diagram (NOT TO SCALE)



Route 70 westbound



Michael V Feeney

200