

New Jersey Police Crash Investigation Report												Case Number 2018-00022077			Page 2 of 3	
	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death		
E																
F																
G																
H																
I																
J																

144. Crash Diagram



Show NORTH by Arrow
(Not to Scale)

SEE ATTACHED DIAGRAM

145. Crash Description/Narrative

Vehicle 1 and 2 were traveling west on Route 88. Vehicle 2 was stopped in traffic. While vehicle 2 was stopped,

vehicle 1 continued traveling west and crashed into the rear of vehicle 2, causing minor damage. Due to the

accident, vehicle 1 sustained major damage to the front end, causing the vehicle to be disabled in the middle of

the roadway.

When the driver of vehicle 2 came to a rest, he looked in his review mirror and witnessed the driver of vehicle 1

fleeing the scene of the accident. While off-duty, Ptl. Thergesen #249 witnessed the man fleeing toward

Jefferson Dr. Ptl. Thergesen #249 was able to apprehend the driver of vehicle 1 in front of 20 Jefferson Dr.

Due to the impact of the accident, the driver of vehicle 2 requested to be examined by Brick EMS. Brick EMS

evaluated the driver at the scene, but he refused any further medical evaluation at the hospital.

The driver of vehicle 1 refused to give a statement about the events of the accident.

In reference to this accident, see Ptl. Barlowski #284 case form.


146. Officer's Signature John C Rotondo	147. Badge # 252	148. Reviewer Arthur D Rivaldo	Badge # 179	149. Case Status ☐ Pending ☒ Complete
--	---------------------	-----------------------------------	----------------	---

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram

Police Dept: Brick Police Code: 01
Station: Case No: 2018-00022077


144 Crash Diagram (NOT TO SCALE)

○ Indicate
North



J's Garden Spot
2039 RT 88

RT 88



NOT TO SCALE

John C Rotondo

Officer's Signature

252

Badge Number