

☐ Fatal

New Jersey Police Crash Investigation Report

☒ Reportable☐ Non-Reportable☐ Change Report

96	Page 2 of 7		☐ Fatal		New Jersey Police Crash Investigation Report										☒ Reportable		☐ Non-Reportable		☐ Change Report		25																																							
97	1. Case Number				2021-00059943										10. Crash Occurred On:				11. Speed Limit		12. Route No.		Suffix		13. Milepost		18. Speed Limit		118a																															
98	2. Police Dept. of				Code		Brick Police										01		Road Name										Dir		14										15		16		19. To: 17. Cross Road Name/Route No.										NB		EB		118b	
99	3. Station/Precinct																																																										119a	
100a	4. Date of Crash				mm		dd		yy		5. Day of Week				Su		M		Tu		W		6. Time (use 2400 hrs.)				mm		dd		yy		7. Municipality Code				15		16		19. Ramp										20. Route Name/Route No.		21. Latitude		22. Longitude		119b			
100b	23. Veh. #				24. Policy No.		03										25. NJ Ins. Code		53. Veh. #		54. Policy No.		55. NJ Ins. Code										120a																											
101	26. Driver's First Name				Initial		Last Name		29. Sex				56. Driver's First Name		Initial		Last Name		59. Sex				120b																																					
102	27. Number & Street														57. Number & Street												121a																																	
103	28. City				State		Zip		58. City				State		Zip												121b																																	
104	30. Eyes				DL Class		Restrictions		Endorsements		31. State		60. Eyes		DL Class		Restrictions		Endorsements		61. State		122																																					
105	32. Driver's License Number				33. DOB		mm		dd		yy		34. Expires		mm		dd		yy		62. Driver's License Number		63. DOB		mm		dd		yy		64. Expires		mm		yy		123																							
106	35. Owner's First Name				Initial		Last Name		65. Owner's First Name				Initial		Last Name												124																																	
107	36. Number & Street				2 TAYLOR DR										66. Number & Street												125																																	
108	37. City				State		Zip		67. City				State		Zip												126a																																	
109	38. Make				39. Model		40. Color		41. Year		42. Plate No.		43. State		68. Make		69. Model		70. Color		71. Year		72. Plate No.		73. State												126b																							
110	44. VIN				45. Expires		02/22										74. VIN				75. Expires												126c																											
111	46. Vehicle Removed to:														76. Vehicle Removed to:														126d																															
112	☐ Driven				☐ Towed Disabled		☐ Towed Disabled & Impounded		☐ Driven				☐ Towed Disabled		☐ Towed Disabled & Impounded												126e																																	
113	☒ Left at Scene				☐ Towed Impounded		☐ Left at Scene										☐ Towed Impounded												127a																															
114	47. Authority				☐ Owner		☐ Driver		☒ Police		77. Authority				☐ Owner		☐ Driver		☐ Police												127b																													
115	48. Alcohol Drug Test				Given: ☐ No ☐ Yes ☐ Refused		Type: ☐ Breath ☐ Blood ☐ Urine		49. Hazardous Material				☒ None ☐ On Board ☐ Spill		78. Alcohol Drug Test				Given: ☐ No ☐ Yes ☐ Refused		Type: ☐ Breath ☐ Blood ☐ Urine		79. Hazardous Material				☐ None ☐ On Board ☐ Spill												127c																					
116	Results: 0. - - - %				☐ Pending		Hazard Class		Placard No.		Results: 0. - - - %				☐ Pending		Hazard Class		Placard No.												127d																													
117	50. Carrier No.				☐ USDOT		☒ None		51. GVWR / GCWR (trucks & buses only)				☐ ≤ 10,000 lbs.		☐ 10,001 - 26,000 lbs.		☐ ≥ 26,001 lbs.		80. Carrier No.				☐ USDOT		☒ None		81. GVWR / GCWR (trucks & buses only)				☐ ≤ 10,000 lbs.		☐ 10,001 - 26,000 lbs.		☐ ≥ 26,001 lbs.												127e													
	52. Motor Carrier or Government Entity														82. Motor Carrier or Government Entity														128																															
	Number & Street														Number & Street														129																															
	City				State		Zip		City				State		Zip												130																																	
	135. Damage to Other Property				☐ Yes (If Yes, describe)		☐ No		Brick Township, .																				131																															
	401 CHAMBERS BRIDGE RD, BRICK TOWNSHIP, NJ 08723																																		132																									
	Stock fence and park sign																																		133																									
	Oper.				136. Charge		137. Summons No.		Oper.				138. Charge		139. Summons No.												134																																	
	Oper.				140. Charge		141. Summons No.		Oper.				142. Charge		143. Summons No.												135																																	

[illegible]

96	Page 3 of 7 ☐ Fatal		New Jersey Police Crash Investigation Report															☒ Reportable ☐ Non-Reportable ☐ Change Report			118a									
97	1. Case Number 2021-00059943										10. Crash Occurred On: _____										11. Speed Limit [] []		12. Route No. Suffix		13. Milepost		18. Speed Limit [] []		118b	
98	2. Police Dept. of Brick Police										Code 01		Road Name _____ Dir _____ ☐ At Intersection with ☐ N ☐ E ☐ Feet ☐ S ☐ W ☐ Miles										19. To: _____		17. Cross Road Name/Route No.		☐ NB ☐ EB ☐ SB ☐ WB		119a	
99	3. Station/Precinct _____										14 _____		15 _____		16 _____		19. Ramp _____		20. Route Name/Route No.		22. Longitude		119b							
100a	4. Date of Crash mm dd yy 09 04 21				5. Day of Week Su M Tu W Th F Sa Th				6. Time (use 2400 hrs.) 20 00				7. Municipality Code 1506		8. Total Killed		9. Total Injured		21. Latitude		120a									
100b	23. Veh. #				24. Policy No.				25. NJ Ins. Code				53. Veh. #				54. Policy No.				55. NJ Ins. Code				120b					
101	☐ Parked ☐ Ped ☐ Pedalcyclist ☐ Resp. to Emergency ☐ Hit & Run 26. Driver's First Name Initial Last Name										29. Sex		☐ Parked ☐ Ped ☐ Pedalcyclist ☐ Resp. to Emergency ☐ Hit & Run 56. Driver's First Name Initial Last Name										59. Sex		121a					
102	27. Number & Street										57. Number & Street														121b					
103	28. City State Zip										58. City State Zip																			
104	30. Eyes				DL Class		Restrictions		Endorsements		31. State		60. Eyes				DL Class		Restrictions		Endorsements		61. State		122					
105	32. Driver's License Number				33. DOB mm dd yy				34. Expires mm yy				62. Driver's License Number				63. DOB mm dd yy				64. Expires mm yy				123					
106	35. Owner's First Name Initial Last Name										☐ Same as Driver		65. Owner's First Name Initial Last Name										☐ Same as Driver						124	
107	36. Number & Street										66. Number & Street														125					
108	37. City State Zip										67. City State Zip														126a					
109	38. Make		39. Model		40. Color		41. Year		42. Plate No.		43. State		68. Make		69. Model		70. Color		71. Year		72. Plate No.		73. State		126b					
110	44. VIN										45. Expires		74. VIN										75. Expires						126c	
111	46. Vehicle Removed to:										76. Vehicle Removed to:														126d					
112	☐ Driven ☐ Towed Disabled ☐ Towed Disabled & Impounded ☐ Left at Scene ☐ Towed Impounded										☐ Driven ☐ Towed Disabled ☐ Towed Disabled & Impounded ☐ Left at Scene ☐ Towed Impounded														126e					
113	47. Authority ☐ Owner ☐ Driver ☐ Police										77. Authority ☐ Owner ☐ Driver ☐ Police														127a					
114	48. Alcohol Drug Test Given: ☐ No ☐ Yes ☐ Refused Type: ☐ Breath ☐ Blood ☐ Urine Results: 0. [] [] % ☐ Pending				49. Hazardous Material ☐ None ☐ On Board ☐ Spill Hazard Class _____ Placard No. [] [] [] []						78. Alcohol Drug Test Given: ☐ No ☐ Yes ☐ Refused Type: ☐ Breath ☐ Blood ☐ Urine Results: 0. [] [] % ☐ Pending				79. Hazardous Material ☐ None ☐ On Board ☐ Spill Hazard Class _____ Placard No. [] [] [] []						127b									
115																					127c									
116																					127d									
117	50. Carrier No. ☐ USDOT [] [] [] [] ☐ None ☐ MC/MX [] [] [] []				51. GVWR / GCWR (trucks & buses only) ☐ ≤ 10,000 lbs. ☐ 10,001 - 26,000 lbs. ☐ ≥ 26,001 lbs.						80. Carrier No. ☐ USDOT [] [] [] [] ☐ None ☐ MC/MX [] [] [] []				81. GVWR / GCWR (trucks & buses only) ☐ ≤ 10,000 lbs. ☐ 10,001 - 26,000 lbs. ☐ ≥ 26,001 lbs.						127e									
52. Motor Carrier or Government Entity															82. Motor Carrier or Government Entity															128
Number & Street															Number & Street															129
City State Zip															City State Zip															130
135. Damage to Other Property ☐ Yes (If Yes, describe) ☐ No First Energy - JCP&L, . 101 CRAWFORD RD. bldg1 suite 15-11, Middletown Township07748 power lines and utility pole																														131
																														132
Oper. 136. Charge															137. Summons No.															133
Oper. 140. Charge															141. Summons No.															134

	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death
A														
B														
C														
D														

New Jersey Police Crash Investigation Report												Case Number 2021-00059943			Page <u>4</u> of <u>7</u>	
	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death		
E																
F																
G																
H																
I																
J																

144. Crash Diagram



Show NORTH by Arrow
(Not to Scale)

SEE ATTACHED DIAGRAM

145. Crash Description/Narrative

On 09/04/2021 at 2000 hours, multiple officers responded to the area of Drum Point Road and Mandalay Road in reference to a motor vehicle crash. Prior to arrival, dispatch advised one of the vehicles struck a utility pole and there were wires down in the roadway. In addition, the caller advised the white pickup truck passed their house at an estimated 125mph. The first officers on scene, Ptl. Newlund #285 and Ptl. Gordon #297, conducted a preliminary investigation.

The crash involved three vehicles. Vehicle 1 was a Ford F-150 bearing New Jersey registration N65MMS. It was located off to the side of the road, 616 drum Point road, sitting on top of a chain link fence with extensive frontal damage. Ptl. Newlund located the driver (1), Tyler Pratt, sitting in the back seat of a vehicle down the street (see Ptl. Newlund's supplement report). Vehicle 2 was found in the roadway in front of Bayside Auto, 622 Drum Point Road. It had passenger side rear damage in addition to a tire and trunk lid missing. They were found on the opposite side of the roadway adjacent to Angela Hibbard Dog Park. The driver (2), Lynnea Prunkl, of vehicle 2 and passenger, Fay Novoshelski, were adjacent to their vehicle being assisted by bystanders. Vehicle 3 was a Ford F-250 pickup bearing New Jersey registration U24NDD-NJ which was parked unoccupied in the parking lot of Bayside Auto.

The preliminary investigation revealed driver 1 was driving while under the influence of an intoxicated

146. Officer's Signature Daniel W Fogarty	147. Badge # 211	148. Reviewer David J Thergesen	Badge # 249	149. Case Status ☒ Pending ☐ Complete
--	---------------------	------------------------------------	----------------	---

New Jersey Police Crash Investigation Report

Motor Vehicle Crash Description

Police Dept: Brick Police Code: 01Station: — Case No: 2021-00059943

145 Crash Description

liquor or drug. Subsequently, driver 1 was placed under arrest (see Ptl. Gordon's DUI report). He was transported to Ocean Medical Center for his injuries sustained in the crash. The driver and passenger of vehicle 2 were also transported to Ocean Medical Center for their injuries.

The Traffic Safety Unit was requested due to the severity of the accident. I arrived on location and spoke to Ptl. Newlund regarding the situation. It should be noted, the roadway was shut down due to the utility pole being broken in half and live wires in the roadway. On scene witness statements, vehicle occupants, and road evidence revealed the following:

Vehicle 1 was traveling West bound Drum Point Road in the area of Mandalay Road. Vehicle 2 was traveling East bound Drum Point Road in the area of Mandalay Road. While vehicle 2 attempted to make a left turn onto Mandalay Road, vehicle 1 collided with it's rear passenger side. At the point of impact, two sets of gouge marks from the rims of vehicle 2 were left in the roadway 16 feet East of the manhole cover. Vehicle 2 went into a spin and collided with vehicle 3 which was parked in the Bayside Auto parking lot. From the impact vehicle 2 lost it's passenger side rear tire with rim and trunk lid.

Vehicle 1 continued East bound Drum Point Road where the right front tire (tread only) became unattached. The tire was then set in motion by vehicle 1 and collided with a wooden fence breaking it. It deflected back into the roadway. Vehicle 1 continued to run off the roadway to the right colliding with a "No Parking" sign and park children at play sign. Vehicle 1 then collided with utility pole BT6761BK. The pole snapped and the middle segment broke off. Vehicle 1 became airborne spinning 180 degrees landing on the opposite side of the pole. The momentum of vehicle 1 made it continue traveling in reverse through a chain link fence and bushes. Vehicle 1 finally came to rest after its front passenger wheel assembly detached with its rim.

I spoke to an on scene witness who confirmed vehicle 1 was traveling West bound at a high rate of speed with it's front wheel throwing sparks before it collided with the utility pole and fence (see witness statement form and BWC). I responded to Ocean Medical Center to speak to the occupants. At the hospital, I spoke to driver 2, Lynnea Prunkl. Prunkl went on to say, she was traveling East bound Drum Point Road and observed the headlights of vehicle 1 way down the road. When she attempted to make the left turn onto Mandalay Road she was hit by vehicle 1 in her rear panel. Her vehicle went into a "swung around" hitting the parked truck (V3). When she checked on her passenger, Fay Novoshelski, she was in pain and advised she was going to vomit. Novoshelski, then opened the door and vomited. They were both brought to the hospital by EMS. I then spoke to Novoshelski who corroborated Prunkl's statement.

I then spoke to driver 1, Tyler Pratt. He went on to say, he was coming from the dead end side of Drum Point. Specifically, his family summer home at 648 Drum Point Road. While traveling West bound a car cut him off. He then attempted to turn left to avoid them and collided with their vehicle. When the his vehicle finally stopped he kicked the door open because he was unsure if it was in fire. He got out of the vehicle and began

Daniel W Fogarty

211

New Jersey Police Crash Investigation Report

Motor Vehicle Crash Description

Police Dept: Brick Police Code: 01Station: --- Case No: 2021-00059943

145 Crash Description

walking down the street. Although he did not call 911 he stated he asked on lookers for to call for help. In addition, he denied taking any medication or drinking alcoholic beverages this evening. Vehicle 1 was impounded pending investigation.

On 9/8/21, I conducted a follow up investigation at Bayside Auto in the attempt to obtain surveillance video.

I was assisted by the Manager, Jason Archiello, and obtained the video of the accident. The vantage point of the camera is pointing at Drum Point Rd. It was entered into the case file.

On 9/11/21, Ptl. Therghesen and I met with the owner, Jeffrey Pratt, of vehicle 1 at his residence 648 Drum Point Road. He advised he consulted with his attorney and was willing to give consent for us to retrieve the Event Data Recorder data image from vehicle 1. Jeffrey Pratt read the consent to search form and signed it stating he understood.

On 9/16/21, Ptl. Therghesen and Det. Carrington III OCPO responded to the impound lot (PPTD) and retrieved the data image from vehicle 1. The data revealed vehicle 1 was travel at 90.7 mph highest -4.0sec prior to impact and 75.2 mph at impact. It should be noted, vehicle 1 had oversized tires 35x12.50/R20LT on the vehicle which are different then the stock 245/70R17. Furthermore, it is unknown if the EDR was calibrated for the oversize tires.

On 9/29/21, Ptl. Farnkopf #173 and I conducted a time speed test with a exemplar vehicle (patrol vehicle 151) to compare to the video. All calculations were using the highest times to give the benefit to the driver (see Time Speed Worksheet).

The estimated speed of vehicle 1 at the time of crash was between 86 mph and 94 mph. It should be noted, the speed limit traveling West bound prior to Mandalay Road is 35 mph and after is 40 mph.

Driver 1 is found at fault for the accident due to his high rate of speed. In addition, his level of intoxication is unknown pending his blood test results.

*Driver 1 additional summons 39:3-76.2F E21-006056

39:4-98 E21-006588

Daniel W Fogarty

211

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram

Police Dept: Brick Police


Code: 01

Station:

Case No: 2021-00059943

144 Crash Diagram (NOT TO SCALE)

○ Indicate North



Daniel W Fogarty

Officer's Signature

211

Badge Number