

New Jersey Police Crash Investigation Report												Case Number 2018-00012572			Page <u>2</u> of <u>3</u>	
	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants <i>If Deceased, Date & Time of Death</i>		
E																
F																
G																
H																
I																
J																

144. Crash Diagram



Show NORTH by Arrow
(Not to Scale)

SEE ATTACHED DIAGRAM

145. Crash Description/Narrative

Vehicle 2 was stopped in traffic in the middle lane of Route 70 West in the area of Van Zile Road. Vehicle 1 was stopping in traffic in the middle lane of Route 70 West in the area of Van Zile Road. Vehicle 1 did not come to a complete stop, causing the accident.

The Driver of Vehicle 1 stated they were stopping in traffic in the middle lane of Route 70 West in the area of Van Zile Road. The Driver of Vehicle 1 stated she was not able to stop the vehicle before striking the rear of Vehicle 2.

The Driver of Vehicle 2 stated they were stopped in traffic in the middle lane of Route 70 West in the are of Van Zile Road, when the rear of his vehicle was struck by the front of Vehicle 1.

The Driver of Vehicle 2 had a complaint of pain in his upper back, but refused medical attention on scene. There were no other reported injuries. Both vehicles were moved prior to my arrival. Vehicle 2 had minor damage to the rear bumper. The Driver of Vehicle 1 reported no new damage to her vehicle. Both Vehicles were driven from the scene by their respected drivers.


146. Officer's Signature Christopher R Joaquim	147. Badge # 271	148. Reviewer Steven P Gerling	Badge # 148	149. Case Status ☒ Pending ☐ Complete
---	---------------------	-----------------------------------	----------------	---

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram

Police Dept: Brick Police Code: 01
Station: Case No: 2018-00012572

144 Crash Diagram (NOT TO SCALE)

○ Indicate
North



Christopher R Joaquim

Officer's Signature

271

Badge Number