

NJTR-1 (Rev. 01/17)

New Jersey Police Crash Investigation Report												Case Number 2018-00014498			Page 2 of 3	
E F G H I J	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death		

144. Crash Diagram

Show NORTH by Arrow
(Not to Scale)

SEE ATTACHED DIAGRAM

145. Crash Description/Narrative

Vehicle 2 was stopped in traffic at a red traffic signal on RT 88 e/b at the intersection of Post Rd. Vehicle 1 was traveling north on Post Rd and made a left turn onto RT 88 w/b. During the left turn the rear end of Vehicle 1 lost grip with the roadway, spinning Vehicle 1 to face the opposite direction. Vehicle 1 then regained its grip with the roadway and traveled straight into the left front bumper of Vehicle 2.

Driver 1 stated she had almost completed her left turn when she began to hear her rear tires spin and felt the rear of her vehicle swinging out to the left. Driver 1 stated she attempted to stop the vehicle from spinning around by turning the steering wheel all the way to the right and all the way to the left. Driver 1 stated the vehicle eventually stopped, facing the opposite direction. Driver 1 stated as soon as her vehicle stopped spinning, the rear wheels regained grip with the roadway and her vehicle suddenly lunged forward into Vehicle 2.

Driver 2 advised she could not remember if or when she removed her foot from the accelerator during the vehicle's loss of control.

While on scene I observed several icy patches in the roadway in the area of the intersection.

146. Officer's Signature Daniel P Testa	147. Badge # 0265	148. Reviewer Robert A Hine	Badge # 158	149. Case Status ☐ Pending ☒ Complete
--	----------------------	--------------------------------	----------------	---

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram


Police Dept: Brick Police

Code: 01

Station: —

Case No: 2018-00014498

144 Crash Diagram (NOT TO SCALE)



Daniel P Testa

Officer's Signature

0265

Badge Number