

NJTR-1 (Rev. 01/17)

New Jersey Police Crash Investigation Report												Case Number 2018-00014933			Page 2 of 3	
E F G H I J	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death		

144. Crash Diagram

Show NORTH by Arrow
(Not to Scale)

SEE ATTACHED DIAGRAM

145. Crash Description/Narrative

A motor vehicle crash occurred on Route 88 approximately 800 feet west of Van Zile Road. The crash occurred in front of the entrance to Laurel Square (1930 Route 88).

Driver of Vehicle #1 advised she did not realize Vehicle #2 was stopped in front of her. Driver #1 advised she struck the rear of Vehicle #2.

Driver #2 advised he was stopped in traffic when he was struck from behind by Vehicle #1.

There were no reported injuries while on scene.

Vehicle #1 struck the rear of Vehicle #2, causing minor damage to the rear of Vehicle #2. The only damage to Vehicle #2 were four indentations from the license plate of Vehicle #1. Vehicle #1 had no damage.


Vehicle #1 is the at fault driver for following too closely and driver inattention.

146. Officer's Signature Brian R Foley	147. Badge # 247	148. Reviewer Patrick J Cook	Badge # 140	149. Case Status ☐ Pending ☒ Complete
---	---------------------	---------------------------------	----------------	---

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram

Police Dept: Brick Police Code: 01
Station: Case No: 2018-00014933

144 Crash Diagram (NOT TO SCALE)



Brian R Foley

Officer's Signature

247

Badge Number