

New Jersey Police Crash Investigation Report										☒ Reportable ☐ Non-Reportable ☐ Change Report							
Page 1 of 3		☐ Fatal															
1. Case Number 2018-00009404				10. Crash Occurred On: 495 JACK MARTIN BLVD				11. Speed Limit - -		12. Route No. - -		13. Milepost - -		18. Speed Limit - -			
2. Police Dept. of Brick Police				Code 01		Road Name - -				Dir - -		Suffix - -		16. Speed Limit - -			
3. Station/Precinct - -				☐ At Intersection with ☐ Feet ☐ Miles		☐ N ☐ E ☐ S ☐ W		of: - -		19. To: - -		17. Cross Road Name/Route No. - -		☐ NB ☐ EB ☐ SB ☐ WB			
4. Date of Crash mm dd yy 0 2 1 3 1 8				5. Day of Week Su M Tu W Th F Sa 1 1 1 1 1 1 1		6. Time (use 2400 hrs.) mm dd yy 0 8 1 8		7. Municipality Code 1 5 0 6		8. Total Killed - -		9. Total Injured - -		21. Latitude - - . - - - - - - -			
23. Veh. # 01				24. Policy No. F223670-1				25. NJ Ins. Code 426		53. Veh. # 02				54. Policy No. 4079-64-09-93			
☐ Parked ☐ Ped ☐ Pedalcyclist ☐ Resp. to Emergency ☐ Hit & Run				26. Driver's First Name DEMETRIO				29. Sex M		☐ Parked ☐ Ped ☐ Pedalcyclist ☐ Resp. to Emergency ☐ Hit & Run				59. Sex - -			
27. Number & Street 425 EAST MAIN ST.				28. City MANASQUAN				State NJ		Zip 08736				57. Number & Street - -			
30. Eyes 0 2				DL Class D		Restrictions - - - -		Endorsements - -		31. State NJ		60. Eyes - -		DL Class - -		Restrictions - - - -	
32. Driver's License Number 0 5 4 0 4				33. DOB mm dd yy 1 6 2 0 0		34. Expires mm yy 0 2 3 7 2		35. Owner's First Name Initial Last Name DEMETRIO OLIVO		62. Driver's License Number - - - - -				63. DOB mm dd yy - - - - -		64. Expires mm yy - - - - -	
36. Number & Street 425 EAST MAIN ST.				37. City MANASQUAN				State NJ		Zip 08736				66. Number & Street 1422 THOMAS ST			
38. Make Nissan				39. Model MURANO		40. Color BK		41. Year 2017		42. Plate No. B69JGL		43. State NJ		67. City POINT PLEASANT BOROUGH			
44. VIN 5 N 1 A Z 2 M H 5 H N 1 4 1 3 1 0				45. Expires 09/21		46. Vehicle Removed to: ☒ Driven ☐ Towed Disabled ☐ Towed Disabled & Impounded ☐ Left at Scene ☐ Towed Impounded		68. Make Honda				69. Model Civic		70. Color SL		71. Year 2016	
47. Authority ☐ Owner ☒ Driver ☐ Police				48. Alcohol Drug Test Given: ☒ No ☐ Yes ☐ Refused Type: ☐ Breath ☐ Blood ☐ Urine Results: 0. - - % ☐ Pending		49. Hazardous Material ☒ None ☐ On Board ☐ Spill Hazard Class - - - - Placard No. - - - -		74. VIN 2 H G F C 2 F 5 1 G H 5 1 2 4 3 7				75. Expires 01/20		76. Vehicle Removed to: ☒ Driven ☐ Towed Disabled ☐ Towed Disabled & Impounded ☐ Left at Scene ☐ Towed Impounded		77. Authority ☐ Owner ☒ Driver ☐ Police	
50. Carrier No. ☐ USDOT - - - - - ☒ None ☐ MC/MX - - - - -				51. GVWR / GCWR (trucks & buses only) ☐ ≤ 10,000 lbs. ☐ 10,001 - 26,000 lbs. ☐ ≥ 26,001 lbs.		52. Motor Carrier or Government Entity - -		80. Carrier No. ☐ USDOT - - - - - ☒ None ☐ MC/MX - - - - -				81. GVWR / GCWR (trucks & buses only) ☐ ≤ 10,000 lbs. ☐ 10,001 - 26,000 lbs. ☐ ≥ 26,001 lbs.		82. Motor Carrier or Government Entity - -		83. Summons No. - -	
53. Summons No. - -				54. Charge - -		55. Summons No. - -				56. Charge - -		57. Summons No. - -				58. Charge - -	
59. Summons No. - -				60. Charge - -		61. Summons No. - -				62. Charge - -		63. Summons No. - -				64. Charge - -	
65. Summons No. - -				66. Charge - -		67. Summons No. - -				68. Charge - -		69. Summons No. - -				70. Charge - -	
65. Damage to Other Property ☐ Yes (If Yes, describe) ☒ No				66. Summons No. - -		67. Charge - -				68. Summons No. - -		69. Charge - -		70. Summons No. - -		71. Charge - -	
65. Summons No. - -				66. Charge - -		67. Summons No. - -				68. Charge - -		69. Summons No. - -				70. Charge - -	
65. Summons No. - -				66. Charge - -		67. Summons No. - -				68. Charge - -		69. Summons No. - -				70. Charge - -	
65. Summons No. - -				66. Charge - -		67. Summons No. - -				68. Charge - -		69. Summons No. - -				70. Charge - -	
65. Summons No. - -				66. Charge - -		67. Summons No. - -				68. Charge - -		69. Summons No. - -				70. Charge - -	

[illegible]

New Jersey Police Crash Investigation Report												Case Number 2018-00009404			Page 2 of 3	
E F G H I J	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death		

144. Crash Diagram

Show NORTH by Arrow
(Not to Scale)

SEE ATTACHED DIAGRAM

145. Crash Description/Narrative

Vehicle 01's left front struck a parked Vehicle 02 in the right rear door of 495 Jack Martin Blvd.

Owner of Vehicle 02 stated he had parked his vehicle in the parking lot of 495 Jack Martin Blvd at approximately 7am and when he returned at 815am he found the damage to the right rear door.

Vehicle 01 left a note on Vehicle 02's windshield.

I made contact to Helen Olivo who stated that her husband Demetrio Olivo was parking their vehicle at 495 Jack Martin Blvd when he became ill and struck parked Vehicle 02. Helen Olivo believed her husband was having a heart attack and left a quick note on vehicle 02 before driving her husband to the hospital where he was admitted.

146. Officer's Signature Robert Koch	147. Badge # 170	148. Reviewer Joshua A Jenssen	Badge # 225	149. Case Status ☐ Pending ☒ Complete
---	---------------------	-----------------------------------	----------------	---

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram

Police Dept: Brick Police


Code: 01

Station:

Case No: 2018-00009404

144 Crash Diagram (NOT TO SCALE)

○ Indicate
North



Parking Lot



495 Jack Martin Blvd.

Robert Koch

Officer's Signature

170

Badge Number