

NJTR-1 (Rev. 01/17)

New Jersey Police Crash Investigation Report												Case Number 2018-00001925			Page 2 of 3	
E F G H I J	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death		

144. Crash Diagram

Show NORTH by Arrow
(Not to Scale)

SEE ATTACHED DIAGRAM

145. Crash Description/Narrative

V1 was attempting a left turn eastbound onto Olden St. from The Home Depot parking lot located at 1722 Rt. 88. V2 was traveling westbound on Olden St. in the left lane.

D1 stated an unknown vehicle traveling westbound on Olden St. in the right lane had stopped in traffic to allow him to enter the roadway on Olden St. D1 attempted the left turn and did not observe V2 traveling westbound on Olden St. in the left lane. He stated he was unable to avoid being struck by V2 as he was partially in the lane it was traveling in.

D2 stated she was traveling in the left lane on Olden St. approaching Rt. 88 when V1 entered the lane from The Home Depot parking lot. D2 was unable to avoid striking V1 as it was in her lane and partially hidden by the stopped vehicles in the right lane.

Both vehicles were moved prior to my arrival.


146. Officer's Signature Nicole C Borden	147. Badge # 274	148. Reviewer Erik A Olsen	Badge # 185	149. Case Status ☐ Pending ☒ Complete
---	---------------------	-------------------------------	----------------	---

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram

Police Dept: Brick Police Code: 01
Station: Case No: 2018-00001925

144 Crash Diagram (NOT TO SCALE)

○ Indicate
North



Nicole C Borden

Officer's Signature

274

Badge Number