

NJTR-1 (Rev. 01/17)

New Jersey Police Crash Investigation Report												Case Number 2018-00002639			Page 2 of 3	
E F G H I J	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death		

144. Crash Diagram

Show NORTH by Arrow
(Not to Scale)

SEE ATTACHED DIAGRAM

145. Crash Description/Narrative

Vehicle 2 stopped in traffic, Route 88 westbound, approaching Kenneth Place. Vehicle 1 traveling westbound on Route 88, directly behind Vehicle 2.

Driver 2 stated he was stopped in traffic when he was struck from behind by Vehicle 1. Driver 1 stated she was traveling westbound on Route 88 when her purse fell to the floor. She diverted her eyes from the roadway momentarily to retrieve her purse. When she looked back to the roadway, she saw Vehicle 2 stopped directly in front of her. Driver 1 stated she braked, skidded on the wet pavement and struck the rear of Vehicle 2.

146. Officer's Signature John C Boronkas	147. Badge # 165	148. Reviewer Robert A Hine	Badge # 158	149. Case Status ☐ Pending ☒ Complete
---	---------------------	--------------------------------	----------------	---

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram

Police Dept: Brick Police Code: 01
Station: Case No: 2018-00002639

144 Crash Diagram (NOT TO SCALE)


○ Indicate
North

1929 Route 88



1925 Route
88

Kenneth
Place



Route 88

John C Boronkas

165