

New Jersey Police												Case Number			Page <u>2</u> of <u>3</u>		
Crash Investigation Report												2018-00003027					
E F G H I J	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death			

144. Crash Diagram

Show NORTH by Arrow
(Not to Scale)

SEE ATTACHED DIAGRAM

145. Crash Description/Narrative

The driver of vehicle 1 advised he was traveling east bound on Route 88 when a deer ran out in front of his vehicle. As the driver began to stop to avoid striking the deer a second deer entered the road way and struck the passenger's side front of his vehicle.

Vehicle 1 sustained damage to the passenger's side front. There were no reported injuries at the time of the report.

146. Officer's Signature	147. Badge #	148. Reviewer	Badge #	149. Case Status
Daniel P Kenny	253	Steven P Gerling	148	☐ Pending ☒ Complete



New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram

Police Dept: Brick Police Code: 01
Station: Case No: 2018-00003027

144 Crash Diagram (NOT TO SCALE)

○ Indicate
North

Route 88



NOT TO SCALE

Daniel P Kenny

Officer's Signature

253

Badge Number