

New Jersey Police Crash Investigation Report												Case Number 2021-00071581			Page <u>2</u> of <u>3</u>	
E F G H I J	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death		

144. Crash Diagram

Show NORTH by Arrow
(Not to Scale)

SEE ATTACHED DIAGRAM

145. Crash Description/Narrative

My investigation revealed the following: Vehicle 1 was traveling eastbound on Route-88. Vehicle 1, while navigating the curve in the roadway, lost control of his vehicle. Vehicle 1 then ran off the road, crashing into utility pole JC-133-BK with the front of Vehicle 1.

Driver 1 advised, while traveling, his right front tire became loose, ultimately falling off. Driver 1 stated the tire falling off caused him to lose control of the vehicle, colliding with the utility pole, causing significant damage to the front of the vehicle.

It should be noted Driver 1 was arrested and charged with driving while intoxicated 39:4-50. See Case Report by Ptl. Ryan #306 for observations and testing.

There are no injuries to report at this time. No damage to the utility pole occurred during the crash. The owner of the vehicle was provided with a copy of the case number. My department issued body worn camera was active during the investigation.



146. Officer's Signature John Canterelli	147. Badge # 312	148. Reviewer Joseph L Rossi	Badge # 240	149. Case Status ☐ Pending ☒ Complete
---	---------------------	---------------------------------	----------------	---

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram

Police Dept: Brick Police Code: 01
Station: Case No: 2021-00071581

144 Crash Diagram (NOT TO SCALE)

○ Indicate
North



NOT TO SCALE

John Canterelli

Officer's Signature

312

Badge Number