

New Jersey Police Crash Investigation Report												Case Number 2021-00071670			Page 2 of 3	
	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants <i>If Deceased, Date & Time of Death</i>		
E																
F																
G																
H																
I																
J																

144. Crash Diagram



Show NORTH by Arrow
(Not to Scale)

SEE ATTACHED DIAGRAM

145. Crash Description/Narrative

Vehicle 1 was stopped at the stop sign leaving the parking lot of Speedway Gas, 1672 RT 88, on to RT 88. Vehicle 2 had pulled up behind Vehicle 1 at the stop sign. Vehicle 1 began to reverse and impacted Vehicle 2.

Driver 2 advised he was behind vehicle 1 when Driver 1 began to back up. Driver 1 advised Driver 2 he was backing up to park along the side of the parking lot to go into the store.

Driver 1 was not on scene to be spoken to. Driver 1 could not wait on scene for police arrival and he left his insurance information with Driver 2. Driver 1 was not able to be contacted.

Vehicle 1 sustained no damage. The hood of Vehicle 2 became dented and bent.


146. Officer's Signature Michael Zolezi	147. Badge # 269	148. Reviewer Anthony S DeMaio	Badge # 194	149. Case Status ☐ Pending ☒ Complete
--	---------------------	-----------------------------------	----------------	---

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram

Police Dept: Brick Police Code: 01
Station: Case No: 2021-00071670


144 Crash Diagram (NOT TO SCALE)

○ Indicate
North



Parking Lot 1672 Route 88

1672 RT 88



Michael Zolezi

Officer's Signature

269

Badge Number