

New Jersey Police Crash Investigation Report												Case Number 2017-00084143			Page 2 of 3	
E F G H I J	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death		

144. Crash Diagram



Show NORTH by Arrow
(Not to Scale)

SEE ATTACHED DIAGRAM

145. Crash Description/Narrative

Vehicle 1 was traveling East in the parking lot of the Speedway gas station, 1672 Route 88, and Vehicle 2 was backed into a parking stall, facing West and unoccupied. The front bumper of Vehicle 1 impacted the front bumper of Vehicle 2. The operator of Vehicle 1 left the area after a verbal altercation (Reference case report 2017-00084143).

The operator of Vehicle 1 stated she was driving into the parking lot of the Speedway and attempted to park directly in front of Vehicle 2. The operator of Vehicle 1 stated she accidentally pulled too far forward and struck Vehicle 2.

The owner of Vehicle 2 stated he was working at the Speedway and observed Vehicle 1 impact his vehicle while it was parked.

No injuries were reported and Vehicle 1 was not on location upon my arrival. On scene investigation assigned the operator of Vehicle 1 at fault and was issued summons #1506-E17-08311.

146. Officer's Signature Evan Charles Mancini	147. Badge # 0282	148. Reviewer Erik A Olsen	Badge # 185	149. Case Status ☐ Pending ☒ Complete
--	----------------------	-------------------------------	----------------	---

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram


Police Dept: Brick Police

Code: 01

Station:

Case No: 2017-00084143

144 Crash Diagram (NOT TO SCALE)



Evan Charles Mancini

0282