

NJTR-1 (Rev. 01/17)

New Jersey Police Crash Investigation Report												Case Number 2021-00074882			Page 2 of 3	
	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death		
E																
F																
G																
H																
I																
J																

144. Crash Diagram



Show NORTH by Arrow
(Not to Scale)

SEE ATTACHED DIAGRAM

145. Crash Description/Narrative

Two vehicle crash occurred on 11/7/2021 at approximately 1124 hours on Van Zile Rd. near the intersection with Route 70. My body worn camera was on during this investigation.

Driver of vehicle #1 advised she was approaching the intersection with Route 70 on Van Zile Rd. and looked down briefly to adjust the radio and did not see vehicle #2 stopped in traffic in front of her. Driver of vehicle #1 stated she struck vehicle #2 in the rear with the front of her vehicle.

Driver of vehicle #2 advised he was stopped for the red light at the intersection of Route 70 and Van Zile Rd. behind several other cars and was struck in the rear by the front of vehicle #1.

I observed minor damage to the front of vehicle #1 and moderate damage to the rear bumper of vehicle #2.

Driver of vehicle #1 is at fault for the crash for following too closely and driver inattention.


146. Officer's Signature Matthew C Knehr	147. Badge # 295	148. Reviewer Charles P Kelly	Badge # 241	149. Case Status ☐ Pending ☒ Complete
---	---------------------	----------------------------------	----------------	---

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram

Police Dept: Brick Police Code: 01
Station: Case No: 2021-00074882

144 Crash Diagram (NOT TO SCALE)

○ Indicate
North



Matthew C Knehr

Officer's Signature

295

Badge Number