

NJTR-1 (Rev. 01/17)

New Jersey Police Crash Investigation Report												Case Number 2017-00079959			Page 2 of 3	
E F G H I J	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death		
144. Crash Diagram  Show NORTH by Arrow (Not to Scale) SEE ATTACHED DIAGRAM																
145. Crash Description/Narrative On scene investigation concluded: Vehicle #1 was attempting to make a left turn from Olden St. onto Rt. 70 (Eastbound). Vehicle #2 was traveling on the exit ramp from Rt. 70 (Eastbound) heading across Rt. 70 onto Olden St. Vehicle #1 failed to yield the right of way to Vehicle #2 and turned into Vehicle #2 as it crossed over Rt. 70. Driver of Vehicle #1 advised she was attempting to make a left turn from Olden St. onto Rt. 70 and did not observe Vehicle #2 attempting to cross the highway. Driver of Vehicle #1 stated another Vehicle coming from the Rt. 70 exit ramp crossing over the highway stopped to allow her to make the left turn. Driver of Vehicle #1 advised she began the left turn and was struck by Vehicle #2. Driver of Vehicle #2 relayed he was traveling across Rt. 70 from the Rt. 70 (Eastbound) exit ramp. Driver of Vehicle #2 advised as he crossed over Rt. 70 Vehicle #1 made a left turn into his vehicle.																
146. Officer's Signature James M Albanese						147. Badge # 257		148. Reviewer Henry J Drew				Badge # 147		149. Case Status ☐ Pending ☒ Complete		

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram

Police Dept: Brick Police

Code: 01

Station:


Case No: 2017-00079959

144 Crash Diagram (NOT TO SCALE)

○ Indicate
North

Olden Street

NOT TO SCALE



Highway 70

James M Albanese

Officer's Signature

257

Badge Number