

New Jersey Police												Case Number			Page <u>2</u> of <u>3</u>		
Crash Investigation Report												2017-00082199					
E F G H I J	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death			

144. Crash Diagram

Show NORTH by Arrow
(Not to Scale)

SEE ATTACHED DIAGRAM

145. Crash Description/Narrative

Investigation at the scene revealed: Vehicle #2 was stopped in traffic facing southbound on Jack Martin Blvd. just before Chard Pl. Vehicle #1 was stopped in traffic facing southbound on Jack Martin Blvd. just before Chard Pl. behind Vehicle #2. Driver #1's foot slipped off of the brake, and subsequently struck the rear of Vehicle #2 with the front of her vehicle.

Driver #2 stated the following: She was stopped in traffic facing southbound on Jack Martin Blvd. just before Chard Pl. She then felt her vehicle rock forward. She was struck in the rear of her vehicle by the front of Vehicle #1.

Driver #1 stated the following: She was stopped in traffic facing southbound on Jack Martin Blvd. just before Chard Pl. behind Vehicle #2. Her foot slipped off of the brake, and subsequently struck the rear of Vehicle #2 with the front of her vehicle.

Both vehicles were moved prior to my arrival, and there were no reported injuries from either parties at that time.


146. Officer's Signature	147. Badge #	148. Reviewer	Badge #	149. Case Status
Joseph Riccio	0289	Jason M Matthews	210	☒ Pending ☐ Complete

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram

Police Dept: Brick Police Code: 01
Station: Case No: 2017-00082199




144 Crash Diagram (NOT TO SCALE)

○ Indicate
North





NOT TO SCALE

Jack Martin
Blvd.



Chard Pl.



V2

V1

Joseph Riccio

Officer's Signature

0289

Badge Number