

New Jersey Police Crash Investigation Report												Case Number 2017-00074635			Page 2 of 3	
	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death		
E																
F																
G																
H																
I																
J																

144. Crash Diagram



Show NORTH by Arrow
(Not to Scale)

SEE ATTACHED DIAGRAM

145. Crash Description/Narrative

Vehicle 1 and 2 were traveling east on Rt 88 near the intersection with Jefferson Dr. Vehicle 2 was stopped for traffic while trying to make a left turn onto Jefferson Dr. Vehicle 1 failed to observe vehicle 2, colliding with the rear.

Driver 1 stated he was traveling east on Rt 88. Driver 1 explained his vehicles battery light was illuminated and flashing which drew his attention. Driver 1 further explained when he looked up from his instrument cluster vehicle 2 was stopped in front of him. Driver 1 stated he attempted to stop, however he was unable to do so causing him to struck vehicle 2 from the rear.

Driver 2 stated she was traveling eastbound on Rt 88 and was stopped due to traffic while attempting to turn left onto Jefferson Dr. Driver 2 stated she was then struck from the rear by vehicle 1.

Driver 1 was issued a summons for Careless Driving (39:4-97) on summons E17 7487

146. Officer's Signature Chase S Carter	147. Badge # 280	148. Reviewer James L Bartolucci	Badge # 183	149. Case Status ☒ Pending ☐ Complete
--	---------------------	-------------------------------------	----------------	---

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram

Police Dept: Brick Police


Code: 01

Station:

Case No: 2017-00074635

144 Crash Diagram (NOT TO SCALE)


○ Indicate
North



NOT TO SCALE

Jefferson Dr

RT 88



Chase S Carter

Officer's Signature

280

Badge Number