

New Jersey Police Crash Investigation Report												Case Number 2017-00071347			Page <u>2</u> of <u>4</u>	
	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants <i>If Deceased, Date & Time of Death</i>		
E	02	06	01	04	13	F	03	08	01	04	04	—	—	ESTI EPSTEIN 124 CAREY ST LAKEWOOD TOWNSHIP NJ 08701		
F	02	05	01	04	17	F	02	04	01	02	03	—	—	CHAMA EPSTEIN 124 CAREY ST LAKEWOOD TOWNSHIP NJ 08701		
G	02	04	01	—	11	F	—	—	—	04	04	—	—	SARI EPSTEIN 124 CAREY ST LAKEWOOD TOWNSHIP NJ 08701		
H																
I																
J																

144. Crash Diagram



Show NORTH by Arrow
(Not to Scale)

SEE ATTACHED DIAGRAM

145. Crash Description/Narrative

Vehicle #1 was initially stopped at the stop sign on Burrsville Road waiting to make a left onto Route 88.

Vehicle #2 was traveling West on Route 88. Driver #1 pulled out in front of Vehicle #2 in attempt to make the turn, and in doing so he collided with the front of vehicle #2. After the initial collision, both vehicles crossed the centerline, and then struck the curb on the Westbound side of the roadway. Vehicle #1 came to rest after hitting the curb. vehicle #2 continued up onto the sidewalk and then came to rest.

Driver #1 was unsure of what happened initially, stating that everything happened so fast. Passenger #1 advised that they were stopped at the stop sign before pulling out into traffic on Route 88. Driver #2 advised that she was traveling Westbound on Route 88 when Vehicle #1 suddenly pulled out in front of her. The front passenger of Vehicle #2 also provided the same account of what happened. Upon speaking with Driver #1 again at the hospital, he advised that he initially stopped at the stop sign, and then thought it was clear so he pulled out before colliding with Vehicle #2.

Based upon my observations, and statements made by all parties, I find Driver #1 at fault for failing to yield the right of way to Vehicle #2. Both vehicles sustained major damage to the front end, and were towed from

146. Officer's Signature Michael V Bennett II	147. Badge # 279	148. Reviewer Erik A Olsen	Badge # 185	149. Case Status ☐ Pending ☒ Complete
--	---------------------	-------------------------------	----------------	---

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Description

Police Dept: Brick Police Code: 01
Station: Case No: 2017-00071347

145 Crash Description

the scene. All occupants of Vehicle #2 advised they would be following up with their family doctor.

Michael V Bennett II

279

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram

Police Dept: Brick Police


Code: 01

Station:

Case No: 2017-00071347

144 Crash Diagram (NOT TO SCALE)

○ Indicate
North



Michael V Bennett II

Officer's Signature

279

Badge Number