

New Jersey Police Crash Investigation Report												Case Number 2017-00071727			Page 2 of 3	
E F G H I J	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death		

144. Crash Diagram



Show NORTH by Arrow
(Not to Scale)

SEE ATTACHED DIAGRAM

145. Crash Description/Narrative

On scene investigation concluded: Vehicle #1 was traveling in the right lane on Post Rd. attempting to turn left onto Rt. 88. Vehicle #1 proceeded to make the left turn onto Rt. 88 but lost control and exited the roadway to the right. Vehicle #1 struck a curb and then a traffic pole. The traffic pole did not sustain damage during the crash.

Driver of Vehicle #1 advised she was taking the turn from Post Rd. onto Rt. 88 when she lost control of her vehicle. Driver of Vehicle #1 stated her tires were bald, which caused her to lose control on the wet road surface. Driver of Vehicle #1 relayed she slid off the road and hit the curb line.

146. Officer's Signature James M Albanese	147. Badge # 257	148. Reviewer Patrick J Cook	Badge # 140	149. Case Status ☐ Pending ☒ Complete
--	---------------------	---------------------------------	----------------	---

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram

Police Dept: Brick Police


Code: 01

Station:

Case No: 2017-00071727

144 Crash Diagram (NOT TO SCALE)

○ Indicate
North



James M Albanese

Officer's Signature

257

Badge Number