

New Jersey Police Crash Investigation Report												Case Number 2017-00071742			Page 2 of 3	
E F G H I J	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death		

144. Crash Diagram



Show NORTH by Arrow
(Not to Scale)

SEE ATTACHED DIAGRAM

145. Crash Description/Narrative

On scene investigation concluded: Vehicle #1 and Vehicle #2 were traveling in the parking lot of 1500 Rt. 88.

Vehicle #1 was backing out of a parking stall and did not observe Vehicle #2 traveling in the lot. Vehicle #1 backed up and struck Vehicle #2.

Driver of Vehicle #1 advised she was backing out of a parking stall at 1500 Rt. 88 when she struck Vehicle #2.

Driver of Vehicle #1 relayed she looked and did not observe Vehicle #2 but when she backed up, Vehicle #2 was now behind her vehicle.

Driver of Vehicle #2 relayed he was traveling in the parking lot of 1500 Rt. 88 when Vehicle #1 backed up and struck his vehicle.

146. Officer's Signature James M Albanese	147. Badge # 257	148. Reviewer Patrick J Cook	Badge # 140	149. Case Status ☐ Pending ☒ Complete
--	---------------------	---------------------------------	----------------	---

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram

Police Dept: Brick Police


Code: 01

Station:



Case No: 2017-00071742

144 Crash Diagram (NOT TO SCALE)

 Indicate
North



1500 RT. 88



James M Albanese

Officer's Signature

257

Badge Number