

NJTR-1 (Rev. 01/17)

New Jersey Police Crash Investigation Report												Case Number 2017-00066853			Page 2 of 3	
	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants <i>If Deceased, Date & Time of Death</i>		
E																
F																
G																
H																
I																
J																

144. Crash Diagram



Show NORTH by Arrow
(Not to Scale)

SEE ATTACHED DIAGRAM

145. Crash Description/Narrative

The Crash occurred in the parking lot of 495 Jack Martin Blvd. While attempting to park Veh #1's front right bumper struck the left rear bumper of Veh #2.

Driver of Veh #1 stated he pulled into the parking spot, then realized it was a fire zone. While attempting to pull out of the fire zone he struck Veh #2. The Driver of Veh #1 also stated he believes the damage to Veh #2 was there prior to the crash.

The owner of Veh #2 was inside of 495 Jack Martin Blvd at the time of the crash.



146. Officer's Signature Cody Oliverio	147. Badge # 0286	148. Reviewer Joshua A Jenssen	Badge # 225	149. Case Status ☐ Pending ☒ Complete
---	----------------------	-----------------------------------	----------------	---

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram

Police Dept: Brick Police Code: 01
Station: Case No: 2017-00066853

144 Crash Diagram (NOT TO SCALE)

○ Indicate
North



Cody Oliverio

0286