

96	Page 1 of 3	☐ Fatal	New Jersey Police Crash Investigation Report										☒ Reportable	☐ Non-Reportable	☐ Change Report	118a																															
05	1. Case Number		2017-00063472										10. Crash Occurred On: RT 88		11. Speed Limit		3 5		12. Route No.		Suffix		13. Milepost		04																						
01	2. Police Dept. of		Code		Brick Police										01		At Intersection with		☐ N ☐ E		of: Jordan Road		18. Speed Limit		25																						
05	3. Station/Precinct												150		☒ Feet		☐ S ☒ W		19. To: 17. Cross Road Name/Route No.		☐ NB ☐ EB		☐ SB ☐ WB		119b																						
02	4. Date of Crash		5. Day of Week		6. Time (use 2400 hrs.)		7. Municipality Code		8. Total Killed		9. Total Injured		21. Latitude		20 Route Name/Route No.		22. Longitude						120a																								
01	0 9 1 7 1 7		M Tu W Th F Sa		1 9 3 1		1 5 0 6																01																								
100b	23. Veh. #		24. Policy No.		25. NJ Ins. Code		53. Veh. #		54. Policy No.		55. NJ Ins. Code												120b																								
04	01		8392718		096		02		909 799 843		054												121a																								
02	26. Driver's First Name		Initial		Last Name		29. Sex		56. Driver's First Name		Initial		Last Name		59. Sex								01																								
01	SALVATORE		J		MANTO		M		DAWN		M		MAURO		F								121b																								
01	27. Number & Street		28 MAIN ST										57. Number & Street		631 1ST AVE																																
01	28. City		State		Zip		58. City		State		Zip																																				
02	FARMINGDALE		NJ		07727		POINT PLEASANT BOROUGH		NJ		08742												122																								
	30. Eyes		DL Class		Restrictions		Endorsements		31. State		60. Eyes		DL Class		Restrictions		Endorsements		61. State				03																								
	0 2		D		0				NJ		0 2		D						NJ				123																								
105	32. Driver's License Number		33. DOB		34. Expires		62. Driver's License Number		63. DOB		64. Expires												01																								
03	M 0 4 8 8		6 8 6 7 1		0 4 6 5 2		0 4 2 2 6 5		0 4 2 2 0		M 0 8 9 5		1 5 7 7 4		5 4 7 1 2		0 4 2 2 7 1		0 9 2 1																												
	35. Owner's First Name		Initial		Last Name		65. Owner's First Name		Initial		Last Name												124																								
	☒ Same as Driver		SALVATORE J		MANTO		☐ Same as Driver		Vault														04																								
	36. Number & Street		28 MAIN ST										66. Number & Street		3104 UNIONVILLE RD																																
01	37. City		State		Zip		67. City		State		Zip												126a																								
04	FARMINGDALE		NJ		07727		Cranberry Twp		PA		16066												26																								
01	38. Make		39. Model		40. Color		41. Year		42. Plate No.		43. State		68. Make		69. Model		70. Color		71. Year		72. Plate No.		126b																								
01	Acura		TL		SL		1999		ZNS64U		NJ		JEEP		Grand Cher		WT		2015		L81GGG		NJ	—																							
01	44. VIN		1 9 U U A 5 6 4 1 X A 0 4 6 0 2 7										45. Expires		74. VIN		1 C 4 R J F B G X F C 1 7 1 4 7 5										75. Expires		126c																		
01													03/18																02/19		126d																
	46. Vehicle Removed to:												76. Vehicle Removed to:																126e																		
	☒ Driven		☐ Towed Disabled		☐ Towed Disabled & Impounded		☒ Driven		☐ Towed Disabled		☐ Towed Disabled & Impounded												26																								
	☐ Left at Scene		☐ Towed Impounded				☐ Left at Scene		☐ Towed Impounded														127a																								
	47. Authority		☐ Owner ☒ Driver ☐ Police										77. Authority		☐ Owner ☒ Driver ☐ Police												127b																				
	48. Alcohol Drug Test		Given: ☒ No ☐ Yes ☐ Refused										49. Hazardous Material		Given: ☒ No ☐ Yes ☐ Refused										79. Hazardous Material		☒ None ☐ On Board ☐ Spill										127c										
	Type: ☐ Breath ☐ Blood ☐ Urine												Type: ☐ Breath ☐ Blood ☐ Urine												Type: ☐ Breath ☐ Blood ☐ Urine												127d										
	Results: 0. -- % ☐ Pending												Hazard Class		Placard No.										Results: 0. -- % ☐ Pending		Hazard Class										Placard No.										127e
03	50. Carrier No.		☐ USDOT ☒ None										51. GVWR / GCWR (trucks & buses only)		☐ USDOT ☒ None										81. GVWR / GCWR (trucks & buses only)		☐ USDOT ☒ None										128										
02	☐ MC/MX												☐ ≤ 10,000 lbs.		☐ ≤ 10,000 lbs.										☐ 10,001 - 26,000 lbs.		☐ 10,001 - 26,000 lbs.										☐ ≥ 26,001 lbs.		26								
	52. Motor Carrier or Government Entity												82. Motor Carrier or Government Entity																		129																
	Number & Street												Number & Street																		130																
	City		State		Zip		City		State		Zip												131																								
	135. Damage to Other Property		☐ Yes (If Yes, describe) ☒ No																												07																
	Oper. 01		136. Charge 39:4-97										137. Summons No. E17006524		Oper. —		138. Charge —										139. Summons No. —		133																		
	Oper. —		140. Charge —										141. Summons No. —		Oper. —		142. Charge —										143. Summons No. —		134																		

	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death
A	01	01	01	—	52	M	—	—	—	11	04	—	—	SALVATORE J MANTO 28 MAIN ST FARMINGDALE NJ 07727
B	02	01	01	—	46	F	—	—	—	11	04	—	—	DAWN M MAURO 631 1ST AVE POINT PLEASANT BOROUGH NJ 08742
C														
D														

New Jersey Police Crash Investigation Report												Case Number 2017-00063472			Page 2 of 3	
E F G H I J	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death		

144. Crash Diagram

Show NORTH by Arrow
(Not to Scale)

SEE ATTACHED DIAGRAM

145. Crash Description/Narrative

Vehicle 2 traveling eastbound on Route 88 approaching Jordan Road. Vehicle 1 attempting a left turn onto Route 88 eastbound from a driveway in the vicinity of 2214 Route 88.

Driver 2 stated she was traveling on Route 88 eastbound when she saw Vehicle 1 attempting a left turn and was concerned as to how close the vehicle was to hers. Driver 2 was unable to react before being struck on the driver's side rear by Vehicle 1.

Driver 1 stated he was trying to make a left turn onto Route 88 eastbound and did not see Vehicle 2 traveling down the road. Driver 1 stated as he was making his turn, he struck the driver's side rear of Vehicle 2.


Vehicle 1 had damage to the front passenger side bumper area and Vehicle 2 had damage to the driver's side rear wheel and rear quarter panel area.

146. Officer's Signature John C Boronkas	147. Badge # 165	148. Reviewer —	Badge # —	149. Case Status ☐ Pending ☒ Complete
--	--------------------------------	-------------------------------	-------------------------	--

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram

Police Dept: Brick Police Code: 01
Station: Case No: 2017-00063472

144 Crash Diagram (NOT TO SCALE)



John C Boronkas

Officer's Signature

165

Badge Number