

NJTR-1 (Rev. 01/17)

New Jersey Police Crash Investigation Report												Case Number 2017-00065285			Page <u>2</u> of <u>4</u>	
	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants <i>If Deceased, Date & Time of Death</i>		
E																
F																
G																
H																
I																
J																

144. Crash Diagram



Show NORTH by Arrow
(Not to Scale)

SEE ATTACHED DIAGRAM

145. Crash Description/Narrative

Investigation at the scene revealed: Vehicle 1 (Jeep Renegade) was traveling south on Central Ave. and was stopped at the stop sign for the intersection of Beacon Ave. Vehicle 2 was traveling west on Beacon Ave and was approaching the intersection of Central Ave. Vehicle 1 did not see vehicle 2 approaching, and attempted to cross Beacon Ave. Vehicle 1 pulled into vehicle 2's path of travel, causing the front of vehicle 2 to collide with the left rear of vehicle 1. Vehicle 1 then spun in a counter clock wise direction, causing the right rear of Vehicle 1 to collide with the curb on the south west corner of the intersection.

Driver 1 stated she stopped at the stop sign on Central Ave. She looked both ways then proceeded straight, through the intersection. While traveling, Vehicle #2 came out of no where heading west on Beacon Ave and collided with the driver side rear wheel. Driver 1 stated the impact from the crash caused her vehicle to spin counter clock wise until the passenger side rear wheel came into contact with the curb on the south west corner of the intersection.

Driver #2 stated she was traveling west on Beacon Ave, while traveling through the intersection, Vehicle 1 pulled out in front of her. Driver 2 stated she attempted to stop but it was too late.

146. Officer's Signature Matthew Firreno	147. Badge # 283	148. Reviewer Arthur D Rivaldo	Badge # 179	149. Case Status ☐ Pending ☒ Complete
--	----------------------------	--	-----------------------	---

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Description

Police Dept: Brick Police Code: 01
Station: — Case No: 2017-00065285

145 Crash Description

From statements given and observations made on scene. I find vehicle 1 at fault for not yielding properly after being stopped at the stop sign.

Both vehicles were moved prior to my arrival.

Vehicle #1's damage to the driver side rear wheel was disabling. Vehicle #1 was towed by Sandy's Auto Center.

Vehicle #2 suffered minor damage to its front bumper and grill.

Matthew Firreno

283

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram

Police Dept: Brick Police


Code: 01

Station:

Case No: 2017-00065285

144 Crash Diagram (NOT TO SCALE)

○ Indicate North



Matthew Firreno

Officer's Signature

283

Badge Number