

NJTR-1 (Rev. 01/17)

**New Jersey Police
Crash Investigation Report**

Case Number
2017-00061372

Page **2** of **3**

	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death
E														
F														
G														
H														
I														
J														

144. Crash Diagram



Show NORTH by Arrow
(Not to Scale)

SEE ATTACHED DIAGRAM

145. Crash Description/Narrative

Vehicle 2 legally parked facing northbound in the parking lot of Walmart, 1872 Route 88. Vehicle 1 attempting to park directly alongside Vehicle 2.

Vehicle 2 owner stated she was in the store for approximately 25 minutes. When she returned to her car, she found an unknown vehicle had struck the passenger side rear of her vehicle and then left the area.

Based on the damage, it appears Vehicle 1 was attempting to pull into the parking space alongside Vehicle 2, misjudged and struck the passenger side rear. It appears black paint and or plastic was transferred from Vehicle 1 onto Vehicle 2.

146. Officer's Signature

John C Boronkas

147. Badge #

165

148. Reviewer

Joshua A Jenssen

Badge #

225

149. Case Status

☐ Pending ☒ Complete

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram

Police Dept: **Brick Police**

Code: **01**


Station: _____

Case No: **2017-00061372**

144 Crash Diagram (NOT TO SCALE)

○ Indicate
North

Walmart
1872
Route 88



John C Boronkas

165