

96	05	Page 1 of 3	☐ Fatal	New Jersey Police Crash Investigation Report										☐ Reportable	☒ Non-Reportable	☐ Change Report	118a																			
97	01	1. Case Number		2017-00062049										10. Crash Occurred On: Jack Martin BLVD		N	11. Speed Limit	4	0	118b																
98	01	2. Police Dept. of		Code		Brick Police 01										Road Name		Dir	12. Route No.	Suffix	13. Milepost	118c														
99	05	3. Station/Precinct				-										At Intersection with		☒ Feet	☒ S	☐ E	☐ W	14	15	16	118d											
100a	01	4. Date of Crash		5. Day of Week		8. Time (use 2400 hrs.)		7. Municipality Code		8. Total Killed		9. Total Injured		19. Ramp		17. Cross Road Name/Route No.		21. Latitude		22. Longitude		118e														
100b	04	23. Veh. #		24. Policy No.		25. NJ Ins. Code		53. Veh. #		54. Policy No.		55. NJ Ins. Code		26. Driver's First Name		Initial		Last Name		29. Sex		119a														
101	02	01		17399972		135		02		HPA00001077315		413		Paula Groppe						F		119b														
102	01	27. Number & Street		43 White Swan WAY										57. Number & Street		1825 Hovsons BLVD										119c										
103	01	28. City		State		Zip		58. City		State		Zip		Brick		NJ		08723		Toms River		NJ		119d												
104	02	30. Eyes		DL Class		Restrictions		Endorsements		31. State		60. Eyes		DL Class		Restrictions		Endorsements		61. State		122														
105	01	0		2		D		-		NJ		0		4		D		-		NJ		01														
106	---	32. Driver's License Number		33. DOB		34. Expires		62. Driver's License Number		63. DOB		64. Expires		35. Owner's First Name		Initial		Last Name		65. Owner's First Name		Initial		Last Name		122b										
107	---	G 7 5 6 7		6 1 9 7 1		5 2 3 3 2		0 2 2 4 3 3		0 8 1 9		G 4 5 3 6		4 5 7 7 7		5 8 4 3 4		0 8 1 1 4 3		0 9 2 0		123														
108	04	36. Number & Street		SAME										66. Number & Street		SAME										124										
109	01	37. City		State		Zip		67. City		State		Zip		38. Make		39. Model		40. Color		41. Year		42. Plate No.		43. State		124a										
110	01	SAME		SAME		SAME		SAME		SAME		SAME		LEXUS		RX300		WT		2014		L76GPL		NJ		124b										
111	01	44. VIN		45. Expires		74. VIN		75. Expires		46. Vehicle Removed to:		76. Vehicle Removed to:										47. Authority		77. Authority		48. Alcohol Drug Test		49. Hazardous Material		78. Alcohol Drug Test		79. Hazardous Material		125		
112	---	2		06/18		1		02/20		---		---										☒ Owner		☒ Driver		☐ Police		Given: ☒ No ☐ Yes ☐ Refused		☒ None ☐ On Board ☐ Spill		Given: ☒ No ☐ Yes ☐ Refused		☒ None ☐ On Board ☐ Spill		125a
113	---	50. Carrier No.		51. GVWR / GCWR (trucks & buses only)		80. Carrier No.		81. GVWR / GCWR (trucks & buses only)		52. Motor Carrier or Government Entity		82. Motor Carrier or Government Entity										53. Damage to Other Property		Yes (If Yes, describe)		☒ No		130								
114	01	---		---		---		---		---		---										135. Damage to Other Property		Yes (If Yes, describe)		☒ No		131								
115	---	136. Charge		137. Summons No.										138. Charge		139. Summons No.										132										
116	01	140. Charge		141. Summons No.										142. Charge		143. Summons No.										133										
117	01	---		---										---		---										134										

	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death
A	01	01	01	--	84	F	--	--	---	11	04	--	--	Paula Groppe 43 White Swan WAY Brick NJ 08723
B	02	01	01	--	74	F	--	--	---	11	04	--	--	Lenore Giokas 1825 Hovsons BLVD Toms River NJ 08753
C														
D														

**New Jersey Police
Crash Investigation Report**

Case Number
2017-00062049

Page **2** of **3**

	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death
E														
F														
G														
H														
I														
J														

144. Crash Diagram



Show NORTH by Arrow
(Not to Scale)

SEE ATTACHED DIAGRAM

145. Crash Description/Narrative

Vehicle #1 was traveling North on Jack Martin Blvd. directly behind Vehicle #2. Vehicle #2 was stopped in traffic behind a vehicle waiting to turn left into the parking lot entrance of 457 Jack Martin Blvd. The front license plate bracket of Vehicle #1 struck the rear bumper of Vehicle #2.

The operator of Vehicle #1 stated she was traveling on Jack Martin Blvd. and observed Vehicle #2 stop short, directly in front of her vehicle. The operator of Vehicle #1 stated she was unable to stop and avoid Vehicle #2 and struck the rear bumper. She also stated that she had ample room while driving behind Vehicle #2, but was unable to avoid the collision due to Vehicle #2 stopping short.

The operator of Vehicle #2 stated she was traveling on Jack Martin Blvd. and stopped short for a vehicle traveling directly in front of her, which had quickly came to a stop in the roadway. She stated the vehicle in front of her stopped short to turn into the parking lot of 457 Jack Martin Blvd. and as she stopped, Vehicle #1 lightly struck her rear bumper.

No injuries were reported. On scene investigation concludes the operator of Vehicle #1 at fault for following to closely.

146. Officer's Signature

Evan Charles Mancini

147. Badge #

0282

148. Reviewer

Jason M Matthews

Badge #

210

149. Case Status

☒ Pending ☐ Complete

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram

Police Dept: **Brick Police**

Code: **01**


Station: _____

Case No: **2017-00062049**


144 Crash Diagram (NOT TO SCALE)



457 Jack Martin Blvd



NOT TO SCALE



Evan Charles Mancini

0282