

NJTR-1 (Rev. 01/17)

New Jersey Police Crash Investigation Report												Case Number 2021-00079654			Page 2 of 3	
E F G H I J	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death		

144. Crash Diagram



Show NORTH by Arrow
(Not to Scale)

SEE ATTACHED DIAGRAM

145. Crash Description/Narrative

On November 28, 2021 I responded to the parking lot of At Home {} parking lot for a vehicle verse deer crash.

Upon arrival, I observed moderate front driver side damage to the vehicle.

Driver #1 explained she was traveling on Route 88 Eastbound when a deer ran across the street and ran into her vehicle. Once she was struck by the deer she pulled into the At Home parking lot and called the police. There were no reported injuries.


146. Officer's Signature John O Scott	147. Badge # 266	148. Reviewer Jason R Shepherd	Badge # 167	149. Case Status ☐ Pending ☒ Complete
--	---------------------	-----------------------------------	----------------	---

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram

Police Dept: Brick Police Code: 01
Station: Case No: 2021-00079654

144 Crash Diagram (NOT TO SCALE)

○ Indicate
North



Not To Scale

Route 88 Eastbound

Kenneth
Ave



John O Scott

Officer's Signature

266

Badge Number