

Page 2 of 3

Names & Addresses of Occupants
If Deceased, Date & Time of Death

Show NORTH by Arrow
(Not to Scale)

SEE ATTACHED DIAGRAM

Vehicle 1 struck vehicle 2 which was parked in the parking lot of Taylor Sam's (1643 Route 88).

The owner of vehicle 2 stated he was parked in the lot to eat for approximately 1 hour and when he returned to this vehicle he observed moderate damage to his front driver side door.

There was no video evidence obtained and no known suspects. Vehicle 2 was driven from the scene and no further information was obtained.


149. Case Status
☐ Pending ☒ Complete

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram

Police Dept: Brick Police Code: 01
Station: Case No: 2021-00080037


144 Crash Diagram (NOT TO SCALE)

○ Indicate
North



Not To Scale

1643 RT 88
Taylor Sam's



Carissa Pagnotta

Officer's Signature

301

Badge Number