

NJTR-1 (Rev. 01/17)

New Jersey Police												Case Number			Page <u>2</u> of <u>3</u>		
Crash Investigation Report												2021-00077738					
	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death			
E F G H I J																	

144. Crash Diagram

Show NORTH by Arrow
(Not to Scale)

SEE ATTACHED DIAGRAM

145. Crash Description/Narrative

Vehicle 2 was parked in a valet parking space at Brick Hospital, 425 Jack Martin Blvd. When the owner of the

vehicle took custody of her vehicle she noticed damage on the passenger side rear fender. The owner of the

vehicle believes it happened while it was parked in the hospital lot. No paint transfer was observed. The only

observable damage was the passenger side rear fender being pulled out. The area the vehicle was parked in checked

negative for any damaged vehicles. Valet reported the vehicle was not involved in a crash while they were

operating it.



146. Officer's Signature	147. Badge #	148. Reviewer	Badge #	149. Case Status
Michael Zolezi	269	Joshua A Jenssen	225	☐ Pending ☒ Complete

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram

Police Dept: Brick Police Code: 01
Station: Case No: 2021-00077738

144 Crash Diagram (NOT TO SCALE)

○ Indicate
North



Damage

Michael Zolezi

Officer's Signature

269

Badge Number