

Page 1 of 4		New Jersey Police Crash Investigation Report		☒ Reportable ☐ Non-Reportable ☐ Change Report	
96	05	1. Case Number 2021-00078330		10. Crash Occurred On: RT 88	
97	01	2. Police Dept. of Brick Police		Code 01	
98	06	3. Station/Precinct		11. Speed Limit 3 5	
99	02	4. Date of Crash mm dd yy 1 1 2 2 2 1		5. Day of Week Su Mo Tu W Th F Sa Mo	
100a	01	6. Time (use 2400 hrs.) 1 8 5 0		7. Municipality Code 1 5 0 6	
100b	04	23. Veh. # 01		24. Policy No. HPA00002689574	
101	02	26. Driver's First Name DAWN		29. Sex M	
102	01	27. Number & Street 268 KETTLE CREEK RD		28. City Toms River	
103	01	28. City Toms River		State Zip NJ 08753	
104	02	30. Eyes 0 2		DL Class D	
105	07	32. Driver's License Number C 0 5 4 5		33. DOB mm dd yy 1 5 7 7 4	
106	—	35. Owner's First Name FRANCESCO CARBONETTO		36. Number & Street 268 KETTLE CREEK RD	
107	—	36. Number & Street 268 KETTLE CREEK RD		37. City Toms River	
108	04	37. City Toms River		State Zip NJ 08753	
109	04	38. Make —		39. Model —	
110	01	44. VIN S A L Y L 2 R X 3 J A 7 5 3 4 6 6		45. Expires 07/22	
111	01	46. Vehicle Removed to: Glen's Towing		47. Authority Owner Driver Police	
112	—	48. Alcohol Drug Test Given: ☒ No ☐ Yes ☐ Refused Type: ☐ Breath ☐ Blood ☐ Urine Results: 0. — % ☐ Pending		49. Hazardous Material ☒ None ☐ On Board ☐ Spill Hazard Class Placard No.	
113	—	50. Carrier No. ☐ USDOT ☒ None		51. GVWR / GCWR (trucks & buses only) ☐ ≤ 10,000 lbs. ☐ 10,001 - 26,000 lbs. ☐ ≥ 26,001 lbs.	
114	—	52. Motor Carrier or Government Entity		53. Veh. # 02	
115	—	54. Policy No. F103574364		55. NJ Ins. Code 426	
116	02	56. Driver's First Name RACHEL		59. Sex F	
117	03	57. Number & Street 28 HIGGINS CT		58. City Howell	
		58. City Howell		State Zip NJ 07731	
		60. Eyes 0 2		DL Class D	
		62. Driver's License Number P 6 1 5 5		63. DOB mm dd yy 6 3 7 7 4	
		65. Owner's First Name KRISTIN M POGREBNEAK		66. Number & Street 28 HIGGINS CT	
		66. Number & Street 28 HIGGINS CT		67. City Howell	
		67. City Howell		State Zip NJ 07731	
		68. Make Hyundai		69. Model Santa Fe	
		70. Color WT		71. Year 2019	
		72. Plate No. A44LNP		73. State NJ	
		74. VIN 5 N M S 2 C A D 8 K H 1 2 8 5 9 2		75. Expires 07/23	
		76. Vehicle Removed to: Surfside Collision		77. Authority Owner Driver Police	
		78. Alcohol Drug Test Given: ☒ No ☐ Yes ☐ Refused Type: ☐ Breath ☐ Blood ☐ Urine Results: 0. — % ☐ Pending		79. Hazardous Material ☒ None ☐ On Board ☐ Spill Hazard Class Placard No.	
		80. Carrier No. ☐ USDOT ☒ None		81. GVWR / GCWR (trucks & buses only) ☐ ≤ 10,000 lbs. ☐ 10,001 - 26,000 lbs. ☐ ≥ 26,001 lbs.	
		82. Motor Carrier or Government Entity		83. Damage to Other Property ☐ Yes (If Yes, describe) ☒ No	
		136. Charge 39:4-97		137. Summons No. E21007425	
		140. Charge		141. Summons No.	
		138. Charge 39:3-76.2F(C)		139. Summons No. E21007426	
		142. Charge		143. Summons No.	
		83		84	
		85		86	
		87		88	
		89		90	
		91		92	
		93		94	
		95		96	
		97		98	
		99		100	
		101		102	
		103		104	
		105		106	
		107		108	
		109		110	
		111		112	
		113		114	
		115		116	
		117		118	
		119		120	
		121		122	
		123		124	
		125		126	
		127		128	
		129		130	
		131		132	
		133		134	
		135		136	
		137		138	
		139		140	
		141		142	
		143		144	
		145		146	
		147		148	
		149		150	
		151		152	
		153		154	
		155		156	
		157		158	
		159		160	
		161		162	
		163		164	
		165		166	
		167		168	
		169		170	
		171		172	
		173		174	
		175		176	
		177		178	
		179		180	
		181		182	
		183		184	
		185		186	
		187		188	
		189		190	
		191		192	
		193		194	
		195		196	
		197		198	
		199		200	
		201		202	
		203		204	
		205		206	
		207		208	
		209		210	
		211		212	
		213		214	
		215		216	
		217		218	
		219		220	
		221		222	
		223		224	
		225		226	
		227		228	
		229		230	
		231		232	
		233		234	
		235		236	
		237		238	
		239		240	
		241		242	
		243		244	
		245		246	
		247		248	
		249		250	
		251		252	
		253		254	
		255		256	
		257		258	
		259		260	
		261		262	
		263		264	
		265		266	
		267		268	
		269		270	
		271		272	
		273		274	
		275		276	
		277		278	
		279		280	
		281		282	
		283		284	
		285		286	
		287		288	
		289		290	
		291		292	
		293		294	
		295		296	
		297		298	
		299		300	
		301		302	
		303		304	
		305		306	
		307		308	
		309		310	
		311		312	
		313		314	
		315		316	
		317		318	
		319		320	
		321		322	
		323		324	
		325		326	
		327		328	
		329		330	
		331		332	
		333		334	
		335		336	
		337		338	
		339		340	
		341		342	
		343		344	
		345		346	
		347		348	
		349		350	
		351		352	
		353		354	
		355		356	
		357		358	
		359		360	
		361		362	
		363		364	
		365		366	
		367		368	
		369		370	
		371		372	
		373		374	
		375		376	
		377		378	
		379		380	
		381		382	
		383		384	
		385		386	
		387		388	
		389		390	
		391		392	
		393		394	
		395		396	
		397		398	
		399		400	
		401		402	
		403		404	
		405		406	
		407		408	
		409		410	
		411		412	
		413		414	
		415		416	
		417		418	
		419		420	
		421		422	
		423		424	
		425		426	
		427		428	
		429		430	
		431		432	
		433		434	
		435		436	
		437		438	
		439		440	
		441		442	
		443		444	
		445		446	
		447		448	
		449		450	
		451		452	
		453		454	
		455		456	
		457		458	
		459		460	
		461		462	
		463		464	
		465		466	
		467		468	
		469		470	
		471		472	
		473		474	
		475		476	
		477		478	
		479		480	
		481		482	
		483		484	
		485		486	
		487		488	
		489		490	
		491		492	
		493		494	
		495		496	
		497		498	
		499		500	
		501		502	
		503		504	
		505		506	
		507		508	
		509		510	
		511		512	
		513		514	
		515		516	
		517		518	
		519		520	
		521		522	
		523		524	
		525		526	
		527		528	
		529		530	
		531		532	
		533		534	
		535		536	

New Jersey Police Crash Investigation Report												Case Number 2021-00078330			Page 2 of 4	
	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death		
E																
F																
G																
H																
I																
J																

144. Crash Diagram



Show NORTH by Arrow
(Not to Scale)

SEE ATTACHED DIAGRAM

145. Crash Description/Narrative

A motor vehicle crash occurred on Route 88 at the intersection with Barb Lane.

Driver of Vehicle #1 advised she was traveling east on Route 88 towards Barb Lane. Driver #1 stated the vehicle traveling west (Vehicle #2) turned at the intersection in front of her vehicle. Driver #1 advised she attempted to brake, but struck Vehicle #2 which was turning left in front of her.

There was disabling damage to the front of Vehicle #1 and also damage to the front passenger side windshield. The front air bags were deployed on this vehicle. Vehicle #1 was towed by Glens Towing.

Driver of Vehicle #2 advised she was traveling on Route 88 west towards Barb Lane. She advised she had a green light and began to turn left onto Barb Lane. Driver #2 did not observe Vehicle #1 and a collision ensued. Initially Driver #2 believed Vehicle #1 traveled through the red light from Jack Martin Blvd.

There was disabling damage to the front passenger side of Vehicle #2. There was air bag deployment. Vehicle #2 was towed by Surfside Towing.

146. Officer's Signature Brian R Foley	147. Badge # 247	148. Reviewer Glenn C Turner	Badge # 178	149. Case Status ☐ Pending ☒ Complete
---	---------------------	---------------------------------	----------------	---

New Jersey Police Crash Investigation Report

Motor Vehicle Crash Description

Police Dept: Brick Police Code: 01Station: — Case No: 2021-00078330

145 Crash Description

The passenger of Vehicle #1 had a large cut on his forehead upon our arrival. He advised when the crash happened he wasn't wearing his seatbelt and struck the windshield. The driver of Vehicle #1 had complaint of pain in her knees. Both parties were transported to Jersey Shore University Medical Center.

There were witnesses to this crash. I spoke to Priscila Morales who advised she was on Jack Martin Blvd and the traffic signal was turning yellow for Route 88. She advised the black vehicle (Vehicle #1) was flying and then the explosion of the crash occurred in front of her. Ptl. Alexander #216 spoke to Joseph Ponce who was on Route 88 westbound when the crash occurred. He advised the traffic signal was green and the white vehicle (Vehicle #2) turned left towards Barb Lane in front of the black vehicle (Vehicle #2).

Vehicle #2 attempted to turn left onto Barb Lane and failed to observe Vehicle #1 traveling east on Route 88, causing a collision in the intersection. When Vehicle #2 was struck, her vehicle slid eastbound towards Barb Lane, striking the curb and finally resting on the sidewalk.

Vehicle #2 is the at fault vehicle for failure to yield right of way to a vehicle and driver inattention. She was issued the following summons: 1506 E21 007425 for 39:4-97, careless driving.

The passenger of Vehicle #1 was issued the following summons: 1506 E21 007426 for 39:3-76.2f(C), failure to wear a seatbelt.

*Vehicle #1 Box 38/39:Range Rover Velar

Brian R Foley

247

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram

Police Dept: Brick Police


Code: 01

Station:

Case No: 2021-00078330

144 Crash Diagram (NOT TO SCALE)

○ Indicate North



Brian R Foley

Officer's Signature

247

Badge Number