

96	Page 1 of 4	Fatal	New Jersey Police Crash Investigation Report	Reportable	Non-Reportable	Change Report	118a
05	1. Case Number	2017-00049958	10. Crash Occurred On: BURRNVILLE RD.	11. Speed Limit	40		02
01	2. Police Dept. of	BRICK TWP. P.D.	Code	01	12. Route No.		118b
01	3. Station/Precinct		14. At Intersection with	15. Feet	16. Miles	17. Cross Road Name/Route No.	03
05	4. Date of Crash	07/23/17	5. Day of Week	Su M Tu W Th F Sa	6. Time (use 2400 hrs.)	1546	119a
01	7. Municipality Code	1506	8. Total Killed		9. Total Injured	1	25
04	23. Veh. #	01	24. Policy No.	4462-73-69-86	25. NJ Ins. Code	148	119b
02	26. Driver's First Name	ESTHER	27. Number & Street	11 MANDARIN CT.	28. City	LAKEWOOD	120a
01	29. State	NJ	30. Zip	08701	31. State	NJ	01
02	32. Driver's License Number	L404123900	33. DOB	62872	34. Expires	0720	121a
03	35. Owner's First Name	NISSAN	36. Number & Street	11 MANDARIN CT.	37. City	LAKEWOOD	121b
01	38. Make	TOYOTA	39. Model	SIENNA	40. Color	SL	122
05	41. Year	2012	42. Plate No.	V71HLN	43. State	NJ	01
01	44. VIN	5TDDK3DC5C5223564	45. Expires	0118	46. Vehicle Removed to:	P.P.T.D.	123
01	47. Authority	Driver	48. Alcohol Drug Test	Given: No Yes Refused	Type: Breath Blood Urine	Results: 0. % Pending	124
02	49. Hazardous Material	None On Board Spill	50. Carrier No.	USDOT MC/MX	51. GVWR / GCWR (trucks & buses only)	≤ 10,000 lbs. 10,001 - 26,000 lbs. ≥ 26,001 lbs.	03
01	52. Motor Carrier or Government Entity		53. Veh. #	02	54. Policy No.	4108-44-97-54	125
01	55. NJ Ins. Code	148	56. Driver's First Name	POOL	57. Number & Street	1646 FORGE POND ROAD.	03
01	58. City	BRICK	59. State	NJ	60. Zip	08724	126a
01	61. State	NJ	62. Driver's License Number	Q9119	63. DOB	63200	26
01	64. Expires	041284	65. Owner's First Name		66. Number & Street		126b
01	67. City		68. Make	TOYOTA	69. Model	4x4	126c
01	70. Color	RD	71. Year	1994	72. Plate No.	N856B3	126d
01	73. State	NJ	74. VIN	JT4RNO1P9R7068600	75. Expires	1117	126e
01	76. Vehicle Removed to:	JDE'S TOWING	77. Authority	Driver	78. Alcohol Drug Test	Given: No Yes Refused	127a
01	79. Hazardous Material	None On Board Spill	80. Carrier No.	USDOT MC/MX	81. GVWR / GCWR (trucks & buses only)	≤ 10,000 lbs. 10,001 - 26,000 lbs. ≥ 26,001 lbs.	26
01	82. Motor Carrier or Government Entity		83. Damage to Other Property	Yes (If Yes, describe) No	84. None		127b
01	85. None		86. None		87. None		127c
01	88. None		89. None		90. None		127d
01	91. None		92. None		93. None		127e
01	94. None		95. None		96. None		128
01	97. None		98. None		99. None		129
01	100. None		101. None		102. None		130
01	103. None		104. None		105. None		03
01	106. None		107. None		108. None		131
01	109. None		110. None		111. None		12
01	112. None		113. None		114. None		132
01	115. None		116. None		117. None		12
01	118. None		119. None		120. None		04
01	121. None		122. None		123. None		04
01	124. None		125. None		126. None		
01	127. None		128. None		129. None		
01	130. None		131. None		132. None		
01	133. None		134. None		135. None		


	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death
A	01	01	01	-	29	F	-	-	-	11	11	04	-	OPERATOR OF VEHICLE 1
B	01	03	01	-	33	M	-	-	-	11	11	04	-	OWNER OF VEHICLE 1
C	01	04	01	-	01	M	-	-	-	06	06	02	-	MICHAEL LIBERMAN 11 MANDARIN CT. LAKEWOOD, NJ 08701
D	01	06	01	-	02	M	-	-	-	05	05	02	-	FAIGEL LIBERMAN " "

New Jersey Police Crash Investigation Report												Case Number 2017-00049958			Page 2 of 4	
	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death		
E	01	07	01	-	06	M	-	-	-	11	11	02	-	YOSSEF Y. LIBERMAN 11 MANDARIN CT LAKEWOOD, NJ 08740		
F	01	08	01	-	08	F	-	-	-	11	11	02	-	MOSHE N. LIBERMAN " "		
G	02	01	01	04	33	M	10	08	02	11	11	01	→	6505 OPERATOR OF VEHICLE 2.		
H	-															
I	-															
J	-															

144. Crash Diagram



Show NORTH by Arrow
(Not to Scale)



145. Crash Description/Narrative

ON SCENE INVESTIGATION CONCLUDES THE FOLLOWING: VEHICLE 1 WAS TRAVELING EAST ON JACK MARTIN BLVD. APPROACHING THE INTERSECTION OF BURSVILLE ROAD. VEHICLE 2 WAS TRAVELING NORTH ON BURSVILLE ROAD APPROACHING THE INTERSECTION OF JACK MARTIN BLVD. VEHICLE 1 PROCEEDED THROUGH THE INTERSECTION AT THE RED TRAFFIC SIGNAL AND VEHICLE 2 STRUCK THE PASSENGER SIDE OF VEHICLE 1 IN THE INTERSECTION.

UPON MY ARRIVAL, I OBSERVED VEHICLE 1 RESTING ON THE EAST SIDE OF BURSVILLE RD IN THE WESTBOUND LANE OF JACK MARTIN BLVD, AND VEHICLE 2 WAS RESTING IN THE MIDDLE OF THE INTERSECTION FACING SOUTH. VEHICLE 1'S PASSENGER SIDE AIR BAGS AND DRIVER AIR BAGS WERE DEPLOYED, AS WELL AS VEHICLE 2'S DRIVER AIR BAG. BRICK POLICE EMS RESPONDED AND TRANSPORTED THE OPERATOR OF VEHICLE 2 TO OCEAN MEDICAL CENTER FOR SUSTAINED HIP AND HEAD INJURIES. THE OCCUPANTS OF VEHICLE 1 DID NOT REPORT ANY INJURIES AND REFUSED MEDICAL ATTENTION.

WHILE ON LOCATION, I SPOKE WITH 3 INDEPENDENT WITNESSES (REFERENCE WITNESS STATEMENT FORMS FOR FURTHER). I RESPONDED TO OMC WITH EMS FOR THE OPERATOR OF VEHICLE 2'S STATEMENT. PTL. DEFLURI #270 ALSO RESPONDED TO OMC. →CONT'D→

146. Officer's Signature PTL A. [Signature] #282	147. Badge # 282	148. Reviewer [Signature] 1195	149. Case Status ☐ Pending ☒ Complete
---	---------------------	-----------------------------------	---

**New Jersey Police
Crash Investigation Report**

Case Number

2017 - 00049958

Page 4 of 4

	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death
E														
F														
G														
H														
I														
J														

144. Crash Diagram



Show NORTH by Arrow
(Not to Scale)

145. Crash Description/Narrative

→ CONT'D → THE OPERATOR OF VEHICLE 1 STATED SHE WAS NOT SURE WHICH DIRECTION SHE WAS TRAVELING AND WAS UNSURE OF THE COLOR OF THE TRAFFIC SIGNAL. THE OPERATOR OF VEHICLE 1 STATED SHE WAS POSSIBLY TRAVELING EAST ON JACK MARTIN BLVD. FROM RT. 88 WHEN SHE WAS APPROACHING THE INTERSECTION OF BURLSVILLE RD. THE OPERATOR OF VEHICLE 1 STATED SHE PROCEEDED THROUGH THE INTERSECTION WHEN SHE WAS STRUCK BY VEHICLE 2.

THE OPERATOR OF VEHICLE 2 STATED HE WAS TRAVELING NORTH ON BURLSVILLE RD APPROACHING THE GREEN TRAFFIC SIGNAL AT THE INTERSECTION OF JACK MARTIN BLVD. HE STATED HE WAS PROCEEDING THROUGH THE INTERSECTION AND VEHICLE 1 RAN THE RED LIGHT CAUSING HIM TO IMPACT THE PASSENGER SIDE OF VEHICLE 1.

BASED ON THE ON SCENE INVESTIGATIONS, WITNESS STATEMENTS, AND POINT OF IMPACT AS WELL AS RESTING POINTS OF THE VEHICLES, THE OPERATOR OF VEHICLE 1 WAS DETERMINED TO BE AT FAULT. VEHICLE 1 WAS REMOVED BY P.P.T.D AND VEHICLE 2 WAS REMOVED BY JOE'S TOWING. THE OPERATOR OF VEHICLE 1 WAS ISSUED SUMMONS #T-154926 FOR 39:4-97.

146. Officer's Signature

Pir. G. M.

147. Badge #

4282

148. Reviewer

Det. Narduk

Badge #

1195

149. Case Status

☐ Pending ☒ Complete