

96	Page 1 of 5		☐ Fatal		New Jersey Police Crash Investigation Report										☒ Reportable		☐ Non-Reportable		☐ Change Report		118a																																				
01	1. Case Number				2021-00083156										10. Crash Occurred On: RT 70				11. Speed Limit		5 0		12. Route No.		13. Milepost		18. Speed Limit		09																												
01	2. Police Dept. of				Code		Brick Police										01												02																												
02	3. Station/Precinct														100		14		15		16		17. Cross Road Name/Route No.		19. To: 17. From: -		20. Route Name/Route No.		21. Latitude		22. Longitude		25																								
02	4. Date of Crash				5. Day of Week		6. Time (use 2400 hrs.)		7. Municipality Code		8. Total Killed		9. Total Injured												07																																
01	1 2 1 4 2 1				Su M Tu W Th F Sa		0 6 1 5		1 5 0 6		-		0 2												07																																
06	23. Veh. #				24. Policy No.		25. NJ Ins. Code		53. Veh. #		54. Policy No.		55. NJ Ins. Code												01																																
01	01				935274199		134		02		3432306		101												01																																
02	26. Driver's First Name				Initial		Last Name		29. Sex		56. Driver's First Name				Initial		Last Name		59. Sex												01																										
01	Edward				E		Wentzheimer		M		Mintaz						Shahhosein		F												01																										
01	27. Number & Street				59 BUCKINGHAM DR C										57. Number & Street				235 SOPHEE LN										01																												
01	28. City				State		Zip		58. City				State		Zip												01																														
03	Lakewood				NJ		08701		Lakewood				NJ		08701												01																														
03	30. Eyes				DL Class		Restrictions		Endorsements		31. State		60. Eyes				DL Class		Restrictions		Endorsements		61. State												01																						
01	0 2				D		-		-		NJ		0 2				D		-		-		NJ												01																						
01	32. Driver's License Number				33. DOB		34. Expires		62. Driver's License Number				63. DOB		64. Expires												07																														
01	W2 5 9 6				1 9 2 6 5		0 5 4 8 2		0 5 2 8 4 8		0 5 2 4		S 3 1 4 4				5 5 7 0 0		5 8 6 2 2		0 8 2 7 6 2		0 8 2 5												07																						
01	35. Owner's First Name				Initial		Last Name		65. Owner's First Name				Initial		Last Name												03																														
01	Same as Driver				Edward E		Wentzheimer		Same as Driver				Mintaz		Shahhosein												03																														
01	36. Number & Street				59 BUCKINGHAM DR C										66. Number & Street				235 SOPHEE LN										03																												
01	37. City				State		Zip		67. City				State		Zip												26																														
04	38. Make				39. Model		40. Color		41. Year		42. Plate No.		43. State		68. Make				69. Model		70. Color		71. Year		72. Plate No.		73. State												26																		
01	L30				SL		2001		Y60LGK		NJ		Chevrolet				Equinox		BK		2021		S46PDL		NJ												26																				
01	44. VIN				1 G 8 J U 5 2 F 6 1 Y 5 9 1 0 1 8										45. Expires				74. VIN				2 G N A X N E V X M 6 1 5 9 3 0 7										75. Expires				08/25										26										
01	46. Vehicle Removed to:				Brick Performance										76. Vehicle Removed to:				Sandys Service Center																				26																		
01	47. Authority				Owner Driver Police										77. Authority				Owner Driver Police																				26																		
01	48. Alcohol Drug Test				Given: No Yes Refused										49. Hazardous Material				Given: No Yes Refused										79. Hazardous Material														26														
01	Type: Breath Blood Urine				Type: Breath Blood Urine										Type: Breath Blood Urine				Type: Breath Blood Urine										Type: Breath Blood Urine														26														
01	Results: 0 % Pending				Results: 0 % Pending										Results: 0 % Pending				Results: 0 % Pending										Results: 0 % Pending														26														
02	50. Carrier No.				USDOT MC/MX										51. GVWR / GCWR (trucks & buses only)				USDOT MC/MX										80. Carrier No.				USDOT MC/MX										81. GVWR / GCWR (trucks & buses only)														26
02	52. Motor Carrier or Government Entity														82. Motor Carrier or Government Entity																																		26								
02	Number & Street														Number & Street																																		12								
02	City				State		Zip		City				State		Zip																						12																				
02	135. Damage to Other Property				Yes (If Yes, describe) No																																								06												
02	136. Charge				39:4-97										137. Summons No.				1506-E21-7720										138. Charge				39:3-4										139. Summons No.				1506-E21-7721										04
02	140. Charge														141. Summons No.														142. Charge														143. Summons No.														04
Names & Addresses of Occupants If Deceased, Date & Time of Death																																																									
A	01	01	01	-	73	M	-	-	02	11	11	01	6505	Edward Earl Wentzheimer 59 BUCKINGHAM DR C Lakewood NJ 08701																																											
B	02	01	01	04	59	F	06	08	02	11	11	01	6505	Mintaz Shahhosein 235 SOPHEE LN Lakewood NJ 08701																																											
C	03	01	01	-	40	F	-	-	-	11	04	-	-	Deborah Lee Gould 411 BIRCH BARK DR BRICK TOWNSHIP NJ 08723																																											
D																																																									

☐ Fatal

New Jersey Police Crash Investigation Report

☒ Reportable☐ Non-Reportable☐ Change Report[illegible][illegible]

New Jersey Police Crash Investigation Report												Case Number 2021-00083156			Page <u>3</u> of <u>5</u>	
	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants <i>If Deceased, Date & Time of Death</i>		
E																
F																
G																
H																
I																
J																

144. Crash Diagram



Show NORTH by Arrow
(Not to Scale)

SEE ATTACHED DIAGRAM

145. Crash Description/Narrative

Investigation revealed Vehicle's 1, 2, and 3 were are traveling eastbound, in the left most lane, on State Highway 70 in the area of State Highway 88. Vehicle 3 was stopped in traffic for a red (stop) traffic signal. Vehicle 2 was slowing down, coming to a stop directly behind Vehicle 3. Vehicle 1 was traveling straight ahead when its front end crashed into the rear end of Vehicle 2. The force of the initial crash caused Vehicle 2's front end to crash into the rear end of Vehicle 3. None of the vehicles were moved prior to police arrival. Vehicle 1 had airbag deployment and sustained disabling damage to its front end (towed form scene); Vehicle 2 had airbag deployment and sustained disabling damage to its front and rear end (towed from scene); and Vehicle 3 sustained moderate, but functional damage to its rear end (driven from scene).

Driver 1 was disoriented and confused about the crash. Driver 1 was unable to recall where he was coming from and traveling too. All he remembered was driving his vehicle and hearing a loud bang. Due to his potential altered mental status, Driver 1 was transported to Ocean Medical Center by EMS, for further evaluation.

Driver 2 stated she was traveling in the left most lane of State Highway 70, directly behind Vehicle 3. As she approached the intersection of State Highway 88, she observed a red (stop) traffic signal, so she began

146. Officer's Signature Kyle W Patrick	147. Badge # 296	148. Reviewer George P Collins	Badge # 186	149. Case Status ☐ Pending ☒ Complete
--	---------------------	-----------------------------------	----------------	---

New Jersey Police Crash Investigation Report
Motor Vehicle Crash DescriptionPolice Dept: Brick Police Code: 01Station: — Case No: 2021-00083156

145 Crash Description

slowing to a stop behind Vehicle 3. While slowing down, her vehicle was struck by Vehicle 1. Driver 2 had a complaint of pain (back), and was transported to Ocean Medical Center by EMS, for further evaluation.

Driver 3 stated she was traveling in the leftmost lane of State Highway 70. As she approached the intersection of State Highway 88, she came to a complete stop at a red (stop) traffic signal. While stopped at the traffic signal, her vehicle was struck by Vehicle 2.

Driver 1's inattention, possible due to his altered mental status, and the fact he was following too closely behind Vehicle 2, was the cause of the crash.

Driver 1 was issued the following summonses:

39:4-97 Careless Driving

39:3-4 Unregistered Motor Vehicle

Kyle W Patrick

296

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram

Police Dept: Brick Police

Code: 01

Station:


Case No: 2021-00083156

144 Crash Diagram (NOT TO SCALE)

○ Indicate
North



NOT TO SCALE



Kyle W Patrick

Officer's Signature

296

Badge Number