

96	Page <u>1</u> of <u>3</u>		New Jersey Police Crash Investigation Report										☒ Reportable		☐ Non-Reportable		☐ Change Report		118a
05	1. Case Number 2017-00048459										10. Crash Occurred On: Route 88		11. Speed Limit 3 5		12. Route No. 88		13. Milepost -		08
01	2. Police Dept. of Brick Township										Code 01		Road Name Jefferson Drive		18. Speed Limit 2 5		118b		
01	3. Station/Precinct										☒ At Intersection with		☐ Feet		☐ Miles		119a		
02	4. Date of Crash 07/17/17										5. Day of Week Th		6. Time (use 2400 hrs.) 1315		7. Municipality Code 1506		8. Total Killed -		25
01	9. Total Injured -										19. To: 17		17. Cross Road Name/Route No.		20. Route Name/Route No.		21. Latitude		119b
01	23. Veh. # 01										24. Policy No. BAS5538782		25. NJ Ins. Code 011		53. Veh. # 02		54. Policy No. 939 464 349		120a
04	26. Driver's First Name Frank										Initial J		Last Name Pfisterer		29. Sex Male		56. Driver's First Name Patricia		120b
02	27. Number & Street 385 Route 35 South										State NJ		Zip 08738		57. Number & Street 108 Harding Drive		58. City Brick Township		121a
01	28. City S Mantoloking										State NJ		Zip 08738		59. Sex Female		121b		
02	30. Eyes 06										DL Class D		Restrictions 01		Endorsements -		61. State NJ		122
01	32. Driver's License Number P3028 26771 05466										33. DOB 05/14/46		34. Expires 01/2/0		62. Driver's License Number S0387 61761 58514		63. DOB 08/24/51		02
01	35. Owner's First Name Comprehensive Risk Mgmt LLC										Initial		Last Name		65. Owner's First Name Patricia		Initial A		123
01	36. Number & Street 1514 State Route 138 Suite 2										State NJ		Zip 07719		66. Number & Street 108 Harding Drive		67. City Brick Township		124
04	37. City Wall										State NJ		Zip 07719		68. Make Lexus		69. Model RX 330		04
04	38. Make Lexus										39. Model RX 330		40. Color Wt		41. Year 2006		42. Plate No. SYE67J		04
02	44. VIN 2 T 2 H A 3 1 U 4 6 C 0 8 7 8 8 3										45. Expires 09/2017		74. VIN J T 3 H P 1 0 V 0 V 7 0 6 2 6 4 6		75. Expires 07/2017		126a		
01	46. Vehicle Removed to:										☒ Driven		☐ Towed Disabled		☐ Towed Disabled & Impounded		126b		
01	47. Authority ☐ Owner ☒ Driver ☐ Police										☐ Left at Scene		☐ Towed Impounded		76. Vehicle Removed to:		126c		
01	48. Alcohol Drug Test Given: ☒ No ☐ Yes ☐ Refused										Type: ☐ Breath ☐ Blood ☐ Urine		Results: 0.00 % ☐ Pending		49. Hazardous Material ☒ None ☐ On Board ☐ Spill		126d		
02	50. Carrier No. ☐ USDOT ☒ None										51. GVWR / GCWR (trucks & buses only) ☐ ≤ 10,000 lbs.		☐ 10,001 - 26,000 lbs.		☐ ≥ 26,001 lbs.		126e		
02	52. Motor Carrier or Government Entity										80. Carrier No. ☐ USDOT ☒ None		81. GVWR / GCWR (trucks & buses only) ☐ ≤ 10,000 lbs.		☐ 10,001 - 26,000 lbs.		127a		
02	135. Damage to Other Property ☐ Yes (If Yes, describe) ☒ No										136. Charge 39:4-97A Careless Driving Causing Property Damage		137. Summons No. 1506-E17-004977		138. Charge -		139. Summons No. -		26
02	140. Charge -										141. Summons No. -		142. Charge -		143. Summons No. -		127b		

	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death
A	V1	01	01	-	71	M	-	-	-	11	04	-	-	Driver of Vehicle #1
B	V2	01	01	-	65	F	-	-	-	11	04	-	-	Driver of Vehicle #2
C	-	-	-	-	-	-	-	-	-	-	-	-	-	
D	-	-	-	-	-	-	-	-	-	-	-	-	-	

New Jersey Police Crash Investigation Report											Case Number 2017-00048459				Page <u>2</u> of <u>3</u>	
	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death		
E	-	-	-	-	-	-	-	-	-	-	-	-	-			
F	-	-	-	-	-	-	-	-	-	-	-	-	-			
G	-	-	-	-	-	-	-	-	-	-	-	-	-			
H	-	-	-	-	-	-	-	-	-	-	-	-	-			
I	-	-	-	-	-	-	-	-	-	-	-	-	-			
J	-	-	-	-	-	-	-	-	-	-	-	-	-			

144. Crash Diagram

Show NORTH by Arrow
(Not to Scale)

S E E
A T T A C H E D

145. Crash Description/Narrative

On 07/17/2017 at approximately 1315 hours, a two car motor vehicle crash occurred on Route 88 east bound in the area of Jefferson Drive. Vehicle #1 was making a right hand turn onto Route 88 east from the parking lot of shore restaurant supply when the vehicle was struck from behind by Vehicle #2.

Driver of Vehicle #1 stated he was making a right hand turn out of the parking lot when he was struck behind by Vehicle #2.

Driver of Vehicle #2 stated Vehicle #1 turned in front of her vehicle without giving her time to stop.


146. Officer's Signature	147. Badge # 276	148. Reviewer	Badge # 202	149. Case Status ☐ Pending ☒ Complete
--------------------------	---------------------	---------------	----------------	---

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram

Police Dept: Brick Police Code: 01
Station: _____ Case No: 2017-00048459

144 Crash Diagram (NOT TO SCALE)

○ Indicate North



Joseph A DeLuca

Officer's Signature

H276

276

Badge Number