

[illegible]

New Jersey Police										Case Number					Page <u>3</u> of <u>4</u>				
Crash Investigation Report										2017-00045909									
	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death					
E																			
F																			
G																			
H																			
I																			
J																			

144. Crash Diagram



Show NORTH by Arrow
(Not to Scale)

SEE ATTACHED DIAGRAM

145. Crash Description/Narrative

Vehicle 1 was traveling south on Jack Martin Blvd. approaching Rt. 70. The crash occurred when vehicle 1 ran off the road to the right and came to rest in the drainage ditch. On scene I observed damage to the front of vehicle 1. No injuries were reported. The vehicle was able to be driven out of the ditch and into a nearby parking area.

The driver of vehicle 1 stated another vehicle had started entering traffic from Falkenberg Dr. which caused her to swerve to the right. She stated she was not sure if she hit her brake or the gas.

146. Officer's Signature Charles P Kelly	147. Badge # 241	148. Reviewer 	Badge # 233	149. Case Status ☐ Pending ☒ Complete
---	---------------------	-------------------	----------------	---

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram

Police Dept: Brick Police


Code: 01

Station: _____

Case No: 2017-00045909

144 Crash Diagram (NOT TO SCALE)

○ Indicate North



Charles P Kelly

241