

[illegible]

**New Jersey Police
Crash Investigation Report**

Case Number
2017-00041962

Page 3 of 4

	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death
E														
F														
G														
H														
I														
J														

144. Crash Diagram



Show NORTH by Arrow
(Not to Scale)

SEE ATTACHED DIAGRAM

145. Crash Description/Narrative

Vehicle 1 was traveling east on Rt. 88 in the area of Bruce St. The crash occurred when vehicle 1 struck a deer while the deer was attempting to cross the roadway. The driver of vehicle 1 could not locate the deer and drove to the nearby parking lot of WalMart and called police.

I observed damage to the left upper front of vehicle 1. I also observed animal hair on the front of the vehicle as well as animal feces. The damage appeared to be the result of striking a deer.

The driver of vehicle 1 stated she was driving when her vehicle was struck. She checked the area for what she hit then moved to the parking lot. I was unable to locate the deer in the area.

146. Officer's Signature
Charles P Kelly

147. Badge #
241

148. Reviewer
[Signature] **119**

149. Case Status
☐ Pending ☒ Complete

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram

Police Dept: Brick Police

Code: 01


Station: _____

Case No: 2017-00041962


144 Crash Diagram (NOT TO SCALE)



Rt. 88



Deer



Bruce St.

Charles P Kelly

241