

Page 1 of 4		New Jersey Police Crash Investigation Report		☒ Reportable ☐ Non-Reportable ☐ Change Report	
96	05	1. Case Number 2017-00033819		10. Crash Occurred On: 1608 Route 88	
97	01	2. Police Dept. of BRICK Twp. Code 101		11. Speed Limit 15	
98	01	3. Station/Precinct		12. Route No. 13. Milepost	
99	09	4. Date of Crash mm dd yy 05/22/17		14. At Intersection with 15. Feet 16. Miles	
100a	01	5. Day of Week Su (M) Tu W Th F Sa		17. Cross Road Name/Route No.	
100b	04	6. Time (use 2400 hrs.) 0648 1506		18. Speed Limit	
101	02	7. Municipality Code 1506		19. To: 17. Ramp	
102	02	8. Total Killed 01		20. Route Name/Route No.	
103	02	9. Total Injured 01		21. Latitude 22. Longitude	
104	02	23. Veh. # 24. Policy No. 01 F5128202		25. NJ Ins. Code 426	
105	08	26. Driver's First Name Initial Last Name Bethy R. Moran		27. Number & Street 18 Capitol Reef Road	
106	04	28. City Howell		29. Sex F	
107	04	30. Eyes DL Class Restrictions Endorsements -2 -D - - - -		31. State NJ	
108	04	32. Driver's License Number M655509179 153752		33. DOB mm dd yy 03/27/75	
109	04	34. Owner's First Name Initial Last Name George A. Moran		35. DOB mm dd yy 08/18	
110	01	36. Number & Street 18 Capitol Reef Road		37. City Howell	
111	01	38. Make 39. Model 40. Color 41. Year 42. Plate No. GMC Acadia SL 2016 AG7FZH NJ		39. Model 40. Color 41. Year 42. Plate No. 4Runner SL 2003 L18AVU NJ	
112	01	43. State NJ		44. VIN JGKKR PKDXGJ10814201/20	
113	01	45. Expires 06/17		46. Vehicle Removed to:	
114	01	47. Authority ☒ Driver		48. Alcohol Drug Test Given: ☒ No ☐ Yes ☐ Refused Type: ☐ Breath ☐ Blood ☐ Urine Results: 0.00 % ☐ Pending	
115	02	49. Hazardous Material ☒ None ☐ On Board ☐ Spill		50. Carrier No. ☐ USDOT ☒ None	
116	01	51. GVWR / GCWR (trucks & buses only) ☐ ≤ 10,000 lbs. ☐ 10,001 - 26,000 lbs. ☐ ≥ 26,001 lbs.		52. Motor Carrier or Government Entity	
117	01	53. Veh. # 54. Policy No. 02 909061387		55. NJ Ins. Code 012	
118a	06	56. Driver's First Name Initial Last Name Dgurin E. Alcerro		57. Number & Street 1227 East Front Street Apt. 7B	
118b	25	58. City Plainfield		59. Sex M	
119a	25	60. Eyes DL Class Restrictions Endorsements -2 -D - - - -		61. State NJ	
119b	25	62. Driver's License Number A517815665 07732		63. DOB mm dd yy 07/20/73	
120a	01	64. Owner's First Name Initial Last Name Liliana Guardado		65. DOB mm dd yy 04/18	
120b	01	66. Number & Street 9 Farragut Rd. Apt. 10A		67. City Plainfield	
121a	01	68. Make 69. Model 70. Color 71. Year 72. Plate No. Toyota 4Runner SL 2003 L18AVU NJ		69. Model 70. Color 71. Year 72. Plate No. 4Runner SL 2003 L18AVU NJ	
121b	01	73. State NJ		74. VIN JTEZU14R830002990	
122	15	75. Expires 06/17		76. Vehicle Removed to:	
123	13	77. Authority ☒ Driver		78. Alcohol Drug Test Given: ☒ No ☐ Yes ☐ Refused Type: ☐ Breath ☐ Blood ☐ Urine Results: 0.00 % ☐ Pending	
124	11	79. Hazardous Material ☒ None ☐ On Board ☐ Spill		80. Carrier No. ☐ USDOT ☒ None	
125	11	81. GVWR / GCWR (trucks & buses only) ☐ ≤ 10,000 lbs. ☐ 10,001 - 26,000 lbs. ☐ ≥ 26,001 lbs.		82. Motor Carrier or Government Entity	
126a	26	83. Damage to Other Property ☐ Yes (If Yes, describe) ☒ No		84. Summons No.	
126b	26	85. Charge		86. Summons No.	
126c	26	87. Charge		88. Summons No.	
126d	26	89. Charge		90. Summons No.	
126e	26	91. Charge		92. Summons No.	
126f	26	93. Charge		94. Summons No.	
126g	26	95. Charge		96. Summons No.	
126h	26	97. Charge		98. Summons No.	
126i	26	99. Charge		100. Summons No.	
126j	26	101. Charge		102. Summons No.	
126k	26	103. Charge		104. Summons No.	
126l	26	105. Charge		106. Summons No.	
126m	26	107. Charge		108. Summons No.	
126n	26	109. Charge		110. Summons No.	
126o	26	111. Charge		112. Summons No.	
126p	26	113. Charge		114. Summons No.	
126q	26	115. Charge		116. Summons No.	
126r	26	117. Charge		118. Summons No.	
126s	26	119. Charge		120. Summons No.	
126t	26	121. Charge		122. Summons No.	
126u	26	123. Charge		124. Summons No.	
126v	26	125. Charge		126. Summons No.	
126w	26	127. Charge		128. Summons No.	
126x	26	129. Charge		130. Summons No.	
126y	26	131. Charge		132. Summons No.	
126z	26	133. Charge		134. Summons No.	

Names & Addresses of Occupants If Deceased, Date & Time of Death														
A	01	01	01	04	42	F	06	08	01	11	04	-	-	Driver of Vehicle #1
B	02	01	01	-	43	M	-	-	-	11	04	-	-	Driver of Vehicle #2
C	-	-	-	-	-	-	-	-	-	-	-	-	-	
D	-	-	-	-	-	-	-	-	-	-	-	-	-	

New Jersey Police Crash Investigation Report										Case Number 2017-00033819					Page <u>3</u> of <u>4</u>	
	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death		
E																
F																
G																
H																
I																
J																

144. Crash Diagram

Show NORTH by Arrow
(Not to Scale)

SEE ATTACHED DIAGRAM

145. Crash Description/Narrative

Crash investigation reveals a two vehicle crash in the parking lot of 1608 Route 88. Vehicle 2 was traveling south in the parking lot attempting to back into a marked parking spot. As vehicle 2 was backing into a marked parking space, the driver of vehicle 1 attempted to pass vehicle 2 as it was backing causing the rear end of vehicle 2 to crash into the rear passenger side of vehicle 1. Driver of vehicle 1 stated vehicle 2 was backing up and came into her lane of travel as she traveled east through the parking lot. Driver of vehicle 2 stated he was backing into a parking spot traveling north at which time vehicle 1 attempted to driver around his vehicle as he was backing. Based on the position of both vehicle 1 and vehicle 2, vehicle 2 had the right of way while backing into a parking spot. Driver of vehicle 1 is at fault for the crash. A witness, who observed the crash, stated vehicle 2 was backing up when vehicle 1 attempted to quickly drive around vehicle 2. The witness filled out and completed a Brick Twp. PD motor vehicle crash statement form. Driver of vehicle 1 complained of minor back pain however, she refused medical attention. No injuries were reported by the driver of vehicle 2. Both vehicles sustained damage and were driven from the scene.

146. Officer's Signature Thomas P Caulfield	147. Badge # 235	148. Review <i>SCT. [Signature]</i>	149. Case Status ☐ Pending ☒ Complete	Badge # <i>179</i>
--	---------------------	--	---	-----------------------

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram

Police Dept: Brick Police


Code: 01

Station: _____

Case No: 2017-00033819


144 Crash Diagram (NOT TO SCALE)

○ Indicate North



NOT TO SCALE

1608 Route 88



Thomas P Caulfield

Officer's Signature

235

Badge Number

179