


96	05	Page 1 of 3	Fatal	New Jersey Police Crash Investigation Report										Reportable	Non-Reportable	Change Report	118a									
97	01	1. Case Number		2017-00030038										10. Crash Occurred On: JACK MARTIN BLVD.		11. Speed Limit		3 5		118b						
98	01	2. Police Dept. of		Code		BRICK 01										Road Name		Dir		12. Route No. Suffix		13. Milepost		18. Speed Limit		119a
99	05	3. Station/Precinct				15										At Intersection with		of: RT 88						4 0		119b
100a	01	4. Date of Crash		5. Day of Week		6. Time		7. Municipality		8. Total Killed		9. Total Injured		19. To: 17. Cross Road Name/Route No.		NB		EB		SB		WB		120a		
100b	04	mm dd yy		Su M Tu W		(use 2400 hrs.)		Code		-		-		Ramp		From:								120b		
101	02	23. Veh. #		24. Policy No.		25. NJ Ins. Code		53. Veh. #		54. Policy No.		55. NJ Ins. Code		21. Latitude		20 Route Name/Route No.		22. Longitude						121a		
102	01	01		PC1608107		*		02		4045-97-27-44		148												121b		
103	01	26. Driver's First Name		Initial		Last Name		29. Sex		56. Driver's First Name		Initial		Last Name		59. Sex								122		
104	02	MARTIN BAUTISTA						M		ROCHELLE LANGSAM						F								123		
		27. Number & Street								57. Number & Street														124		
		15 FULLERTON DR								124 CASE RD														125		
		28. City		State		Zip		58. City		State		Zip												126a		
		BRICK		NJ		08723		LAKEWOOD		NJ		08701												126b		
		30. Eyes		DL Class		Restrictions		Endorsements		31. State		60. Eyes		DL Class		Restrictions		Endorsements		61. State				126c		
		0 2		D -		-		-		NJ		0 4		D -		-		-		NJ				126d		
105	02	32. Driver's License Number		33. DOB		34. Expires		62. Driver's License Number		63. DOB		64. Expires												127a		
		B0901 52500 12712		1 2 0 7 7 1		0 9 1 7		L0426 66000 59614		0 9 0 2 6 1		0 7 1 9												127b		
106	01	35. Owner's First Name		Initial		Last Name		65. Owner's First Name		Initial		Last Name												127c		
107	-	Same as Driver		MANIS TRANSPORTATION				Same as Driver		ROBERT P. LANGSAM														127d		
108	25	36. Number & Street						66. Number & Street																127e		
109	01	15 FULLERTON DR						124 CASE RD																128		
110	02	37. City		State		Zip		67. City		State		Zip												129		
111	01	BRICK		NJ		08723		LAKEWOOD		NJ		08701												130		
112	-	38. Make		39. Model		40. Color		41. Year		42. Plate No.		43. State		68. Make		69. Model		70. Color		71. Year		72. Plate No.		131		
113	-	PTR		TRT		GN		09		AS591R		NJ		DOD		GC		BL		05		YHV70F		132		
114	03	44. VIN		45. Expires				74. VIN		75. Expires														133		
115	-	1 X P X D 4 9 X 6 9 D 7 7 4 3 8 1		7-17				Z D 4 G P 4 4 L 7 5 R 3 6 4 7 9 3		11-17														134		
116	03	46. Vehicle Removed to:						76. Vehicle Removed to:																135		
117	03	☒ Driven ☐ Towed Disabled ☐ Towed Disabled & Impounded						☒ Driven ☐ Towed Disabled ☐ Towed Disabled & Impounded																136		
		☐ Left at Scene ☐ Towed Impounded						☐ Left at Scene ☐ Towed Impounded																137		
		47. Authority		☐ Owner ☒ Driver ☐ Police				77. Authority		☒ Owner ☐ Driver ☐ Police														138		
		48. Alcohol Drug Test		Given: ☒ No ☐ Yes ☐ Refused		49. Hazardous Material		78. Alcohol Drug Test		Given: ☒ No ☐ Yes ☐ Refused		79. Hazardous Material		Given: ☒ No ☐ Yes ☐ Refused		Type: ☐ Breath ☐ Blood ☐ Urine		Type: ☐ Breath ☐ Blood ☐ Urine						139		
		Results: 0. % ☐ Pending				Hazard Class		Placard No.		Results: 0. % ☐ Pending		Hazard Class		Placard No.										140		
		50. Carrier No.		☒ USDOT 1466567 ☐ None		51. GVWR / GCWR (trucks & buses only)		80. Carrier No.		☐ USDOT ☐ None		81. GVWR / GCWR (trucks & buses only)		☐ ≤ 10,000 lbs. ☐ 10,001 - 26,000 lbs. ☒ ≥ 26,001 lbs.										141		
		☐ MC/MX						☐ MC/MX																142		
		52. Motor Carrier or Government Entity		Z TRANSPORTATION INC				82. Motor Carrier or Government Entity																143		
		Number & Street		18 SOUTH 9th ST Suite B 102				Number & Street																144		
		City		State		Zip		City		State		Zip												145		
		STRUODSBURG		PA		18360																		146		
		135. Damage to Other Property		☐ Yes (If Yes, describe) ☒ No																				147		
		Oper.		136. Charge		137. Summons No.		Oper.		138. Charge		139. Summons No.												148		
		-		-		-		-		-		-												149		
		Oper.		140. Charge		141. Summons No.		Oper.		142. Charge		143. Summons No.												150		
		-		-		-		-		-		-												151		

	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death
A	V1	01	01	-	45	M	-	-	-	11	04	-	-	SAME AS DRIVER 1
B	V2	01	01	-	55	F	-	-	-	11	04	-	-	SAME AS DRIVER 2
C	-	-	-	-	-	-	-	-	-	-	-	-	-	
D	-	-	-	-	-	-	-	-	-	-	-	-	-	

New Jersey Police Crash Investigation Report											Case Number 2017-00030038				Page <u>2</u> of <u>3</u>	
	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death		
E																
F																
G																
H																
I																
J																

144. Crash Diagram



Show NORTH by Arrow
(Not to Scale)

SEE ATTACHED DIAGRAM

145. Crash Description/Narrative

As vehicle 1 was attempting to make a right hand turn onto Rt. 88 west from the left lane of Jack Martin Blvd, it struck vehicle 2 who was in the right turn lane of Jack Martin Blvd. Driver 1 stated that due to the size of his semi truck and attached trailer (white HYU Trailer, NJ Reg. TNZ78A), he had to place his vehicle in the left lane, with his turn signal on, so he could make the wide right hand turn onto Rt. 88. When the light turned green, he began his right turn and while checking the right side mirror, he observed the rear right tires of his trailer strike vehicle 2. Driver 1 believed vehicle 2 was attempting to make the right turn ahead of him. Driver 2 stated that she was stopped in the right turn lane on Jack Martin Blvd. just prior to Rt. 88 and was aware that vehicle 1 was attempting to make a right turn. She further stated that she was not going to proceed when the light turned green until vehicle 1 made his turn. As the light turned green, she stated that vehicle 1 began his turn, it's right rear trailer tires impacted the left front driver side door and fender. The investigation revealed that driver 1 failed to notice vehicle 2 in the right lane prior to making the right turn. Glass and debris from vehicle 2 were located at the point of impact approx. 15 feet north of Rt. 88 indicating that vehicle 2 was within it's lane and not attempting to make the right turn before vehicle 1. *Box 25, vehicle 1 is insured by Prime Property And Casualty Inc. 303 W. Madison St. Chicago IL. 1-800-257-5590, policy # PC1608107, exp. 8-3-17. a NJ insurance company code could not be determined.

146. Officer's Signature

[Signature]

147. Badge # 148. Reviewer

222 *[Signature]*

Badge #

105

149. Case Status

☐ Pending ☒ Complete

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram

Police Dept: Brick Police


Code: 01

Station: _____

Case No: 2017-00030038

144 Crash Diagram (NOT TO SCALE)

○ Indicate North



Raymond F LaPoint Jr.

222