

**New Jersey Police
Crash Investigation Report**

Case Number
2017-00027598

Page 2 of 3

	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death
E														
F														
G														
H														
I														
J														

144. Crash Diagram



Show NORTH by Arrow
(Not to Scale)

SEE ATTACHED DIAGRAM

145. Crash Description/Narrative

On 4/25/17 at 0202 hours vehicle #01 a gray Cadillac SRX with NJ reg. Z39FGH was traveling southbound on Jack Martin Blvd. Vehicle # 01 left the roadway to the right and struck a tree approximately 150 feet north of the intersection of Burrsville Rd. Vehicle #01 struck the tree with the front right bumper causing major damage to the vehicle.

The driver of vehicle #01 stated, " I thought the turn was coming up sooner so I started to turn and that is when I hit the tree." He was issued summons # 2746 for 39:4-97 careless driving.

146. Officer's Signature
John D Gordon

147. Badge #
237

148. Reviewer

Badge #

154

149. Case Status


☐ Pending ☒ Complete

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram

Police Dept: _____ Code: _____
Station: _____ Case No: **2017-00027598**

144 Crash Diagram (NOT TO SCALE)

○ Indicate
North



John D Gordon

237