

118a	29	
118b	13	
119a	-	[
119b	-	[
120a	01	
120b	-	[
121a	-	[
121b	-	[
122	09	
123	-	[
124	05	
125	-	[
126a	56	
126b	69	
126c	54	
126d	69	
126e	69	
127a	-	[
127b	-	[
127c	-	[
127d	-	[
127e	69	
128	56	
129	12	
130	12	
131	-	[
132	-	[
133	99	(
134	-	[

[illegible]

New Jersey Police Crash Investigation Report


Case Number

2017-00024921

Page 2 of 2

	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death
E														
F														
G														
H														
I														
J														

144. Crash Diagram



145. Crash Description/Narrative

The driver of Vehicle #1 was parking her vehicle when it surged forward, striking the curb, a landscape timber wall, ran up a hill, striking a fence, and then the exterior of the building at 216 D Jack Martin Blvd. Speaking with the driver she stated that she must have pressed the gas pedal and not the break pedal, causing the crash.

146. Officer's Signature

AR. [Signature]

147. Badge #

183

148. Reviewer

GA [Signature]

Badge #

238

149. Case Status

☐ Pending ☒ Complete