

Page 1 of 2		New Jersey Police Crash Investigation Report		Reportable		Non-Reportable		Change Report	
96	05	1. Case Number 17719-17		10. Crash Occurred On: Jack Martin Blvd		11. Speed Limit 40		12. Route No. 64	
97	01	2. Police Dept. of Brick Township		Code 01		13. Milepost		14. Speed Limit 25	
98	01	3. Station/Precinct		At Intersection with		Chard Pl		15. Speed Limit	
99	05	4. Date of Crash		5. Day of Week		6. Time (use 2400 hrs.)		7. Municipality	
100a	01	03/16/17		Th F Sa		1714		1506	
100b	04	23. Veh. # 01		24. Policy No. PANJ-006504533		25. NJ Ins. Code 071		53. Veh. # 02	
101	02	26. Driver's First Name Christine M Defaranto		29. Sex F		56. Driver's First Name Ellen C Tyndell		59. Sex F	
102	01	27. Number & Street 255 Cedar Island Dr		28. City Brick		29. State NJ		31. State NJ	
103	01	30. Eyes 05		DL Class -D		Restrictions		Endorsements	
104	02	32. Driver's License Number D2840		33. DOB 12/04/76		34. Expires 01/19		62. Driver's License Number T9667	
105	03	35. Owner's First Name James E Allgood		36. Number & Street 259 Cedar Island Dr		37. City Brick		38. Make Maz	
106	-	39. Model Wagen		40. Color BL		41. Year 2006		42. Plate No. S52CVN	
107	-	43. State NJ		44. VIN JM3ER2WMXA0350729		45. Expires 11/17		68. Make CNE	
108	01	46. Vehicle Removed to: DIL Towing		47. Authority Driver		48. Alcohol Drug Test Given: No		49. Hazardous Material None	
109	01	50. Carrier No. USDOT		51. GVWR / GCWR (trucks & buses only)		52. Motor Carrier or Government Entity		53. GVWR / GCWR (trucks & buses only)	
110	01	54. VIN 1G19C5SBL6F7166243		55. Expires 01/19		56. Vehicle Removed to:		57. Authority Driver	
111	01	58. Make Maz		59. Model Wagen		60. Color BL		61. Year 2006	
112	-	62. Plate No. S52CVN		63. State NJ		64. VIN 1G19C5SBL6F7166243		65. Expires 01/19	
113	-	66. Vehicle Removed to:		67. Authority Driver		68. Alcohol Drug Test Given: No		69. Hazardous Material None	
114	-	70. Make Maz		71. Model Wagen		72. Color BL		73. Year 2006	
115	-	74. Plate No. S52CVN		75. State NJ		76. VIN 1G19C5SBL6F7166243		77. Expires 01/19	
116	04	78. Make Maz		79. Model Wagen		80. Color BL		81. Year 2006	
117	01	82. Plate No. S52CVN		83. State NJ		84. VIN 1G19C5SBL6F7166243		85. Expires 01/19	
135. Damage to Other Property Yes (If Yes, describe) No									
Oper. 01		136. Charge 39:4-97A				137. Summons No. E17001615		138. Charge	
Oper. -		140. Charge				141. Summons No.		142. Charge	
Oper. -		143. Summons No.				144. Charge		145. Summons No.	

	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death
A	01	01	01	-	40	F	-	-	-	11	04	-	-	Driver of vehicle 1
B	02	01	01	-	30	F	-	-	-	11	04	-	-	Driver of vehicle 2
C														
D														

New Jersey Police
Crash Investigation Report

Case Number

17719-17


Page 2 of 2

	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death
E														
F														
G														
H														
I														
J														

144. Crash Diagram



Show NORTH by Arrow
(Not to Scale)



145. Crash Description/Narrative

Vehicle 2 was traveling North on Jack Martin Blvd. Vehicle 1 was traveling West on Ocean Park Medical Condo Rd. Vehicle 1 pulled out into traffic to make a left turn to travel South on Jack Martin Blvd and was struck by Vehicle 2.

Driver 2 advised she struck the front driver side of Vehicle 1 when it attempted to make a left turn onto Jack Martin Blvd. Driver 1 advised she believed traffic was clear and attempted to turn off Ocean Park Medical Condo Rd when her vehicle was struck by the front bumper of Vehicle 2.

Based on my observations and statements made by both drivers, I find Driver 1 at fault for careless driving. Driver 1 was issued traffic summons 1506 E17 001665 for 39:4-97A (careless driving).

146. Officer's Signature

[Signature]

147. Badge #

285

148. Reviewer

[Signature]

Badge #

158

149. Case Status

☐ Pending

☒ Complete