

Page 1 of 2 Fatal New Jersey Police Crash Investigation Report Reportable Non-Reportable Change Report

1. Case Number 2017-00045684 10. Crash Occurred On: 425 Jack Martin Boulevard 11. Speed Limit 12. Route No. 13. Milepost 18. Speed Limit

2. Police Dept. of Brick Township 101 3. Station/Precinct 14. At Intersection with 15. Feet 16. Miles 17. Cross Road Name/Route No. 19. Ramp 20. Route Name/Route No. 21. Latitude 22. Longitude

4. Date of Crash 07/06/17 5. Day of Week Th F Sa 6. Time (use 2400 hrs.) 1619 7. Municipality Code 1506 8. Total Killed 9. Total Injured

23. Veh. # 01 24. Policy No. F473590-8 25. NJ Ins. Code 426 53. Veh. # 02 54. Policy No. 187414274 55. NJ Ins. Code 963

26. Driver's First Name Rachelle 27. Number & Street 62 Maplewood Drive 28. City Middletown 29. Sex F 30. Eyes 06 31. State NJ 32. Driver's License Number S7043163761 33. DOB 07/03/69 34. Expires 02/19 35. Owner's First Name Kevin 36. Number & Street 62 Maplewood Drive 37. City Middletown 38. Make Ford 39. Model Fusion 40. Color BK 41. Year 17 42. Plate No. R67HRE 43. State NJ 44. VIN 3FAGP0T94HR302330 45. Expires 3/20 46. Vehicle Removed to: 47. Authority Driver 48. Alcohol Drug Test No 49. Hazardous Material None 50. Carrier No. 51. GVWR / GCWR (trucks & buses only) 52. Motor Carrier or Government Entity

56. Driver's First Name Maria Buro 57. Number & Street 50 Compass Avenue 58. City Brick 59. Sex F 60. Eyes 02 61. State NJ 62. Driver's License Number B9393151900 63. DOB 11/22/35 64. Expires 05/19 65. Owner's First Name 66. Number & Street 67. City 68. Make Toyota 69. Model Matrix 70. Color SL 71. Year 03 72. Plate No. MYG595 73. State NJ 74. VIN 2T1KR32E13C028571 75. Expires 07/18 76. Vehicle Removed to: 77. Authority Driver 78. Alcohol Drug Test No 79. Hazardous Material None 80. Carrier No. 81. GVWR / GCWR (trucks & buses only) 82. Motor Carrier or Government Entity

135. Damage to Other Property Yes (If Yes, describe) No

Oper. 136. Charge 137. Summons No. Oper. 138. Charge 139. Summons No. Oper. 140. Charge 141. Summons No. Oper. 142. Charge 143. Summons No.

	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death
A	01	01	01	-	48	F	-	-	-	11	04	-	-	Driver #1
B	02	01	01	-	81	F	-	-	-	11	04	-	-	Driver #2
C														
D														

New Jersey Police
Crash Investigation Report

Case Number

2017-00045684


Page 2 of 2

	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death
E														
F														
G														
H														
I														
J														

144. Crash Diagram



Show NORTH by Arrow
(Not to Scale)



145. Crash Description/Narrative

Investigation at the scene indicated the following: Vehicle faced west while parked in the parking lot of Brick Hospital. Vehicle 1 backed from the parking space and struck the passenger side of vehicle 2 as vehicle 2 traveled north in the parking lot.

Driver 1 stated the following: Her reverse camera was not working while she backed her vehicle. The rear of her vehicle then struck the passenger side of vehicle 2.

Driver 2 stated the following: She traveled north in the parking lot of Brick Hospital. Vehicle 1 backed from a parking spot as driver 2 began to pass vehicle 1. The passenger side of her vehicle was then struck by the rear of vehicle 1.

146. Officer's Signature

[Signature] 261

147. Badge #

261

148. Reviewer

[Signature]

Badge #

145

149. Case Status

☐ Pending ☒ Complete