

NJTR-1 (Rev. 01/17)

New Jersey Police Crash Investigation Report												Case Number 2021-00019076			Page <u>2</u> of <u>3</u>	
	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants <i>If Deceased, Date & Time of Death</i>		
E																
F																
G																
H																
I																
J																

144. Crash Diagram

Show NORTH by Arrow
(Not to Scale)

SEE ATTACHED DIAGRAM

145. Crash Description/Narrative

Driver 1 stated he was driving eastbound on Duquesne Blvd just past the intersection with Aurora Dr when he struck a pot hole in the roadway. Driver 1 reported the pot hole strike caused the passenger side front tire of vehicle 1 to become damaged.

On scene investigation determined driver 1 was driving eastbound on Duquesne Blvd just past the intersection with Aurora Dr. While driving eastbound, vehicle 1 struck a significant pot hole on the right side of the eastbound lane of travel. I observed damage to vehicle 1's front passenger side tire, where the rubber tire had separated from the tire rim. The damage observed to vehicle 1, as well the size and location of the pot hill is consistent with the statement given by driver 1.

No injuries were reported at the scene.


146. Officer's Signature Kevin Thomas Ryan	147. Badge # 306	148. Reviewer Anthony S DeMaio	Badge # 194	149. Case Status ☐ Pending ☒ Complete
---	---------------------	-----------------------------------	----------------	---

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram

Police Dept: Brick Police Code: 01
Station: Case No: 2021-00019076

144 Crash Diagram (NOT TO SCALE)

○ Indicate
North



Not To Scale

Duquesne Blvd

Aurora Dr

V1

Pot Hole

Kevin Thomas Ryan

Officer's Signature

306

Badge Number