


Page 1 of 3 ☐ Fatal New Jersey Police Crash Investigation Report ☒ Reportable ☐ Non-Reportable ☐ Change Report										118a 02
1. Case Number 2017-00007496										118b 04
2. Police Dept. of Code Brick 01										119a 25
3. Station/Precinct										119b -
10. Crash Occurred On: 1872 Route 88										120b -
Road Name Dir 11. Speed Limit 12. Route No. Suffix 13. Milepost 18. Speed Limit										121a 01
At Intersection with ☐ N ☐ E of: ☐ S ☐ W 19. Ramp 20. Route Name/Route No. 21. Latitude 22. Longitude										121b -
4. Date of Crash 5. Day of Week 6. Time (use 2400 hrs.) 7. Municipality Code 8. Total Killed 9. Total Injured										122 06
mm dd yy Su M Tu W Th F Sa 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31										123 49
23. Veh. # 24. Policy No. 25. NJ Ins. Code 53. Veh. # 54. Policy No. 55. NJ Ins. Code										124 04
01 HPA1253A52668 413 P1										125 04
☐ Parked ☐ Ped ☐ Pedalcyclist ☐ Resp. to Emergency ☐ Hit & Run ☐ Parked ☐ Ped ☐ Pedalcyclist ☐ Resp. to Emergency ☐ Hit & Run										126a 22
26. Driver's First Name Initial Last Name 29. Sex 56. Driver's First Name Initial Last Name 59. Sex										126b -
Walter Ziemba M Kevin Turiano M										126c -
27. Number & Street 57. Number & Street										126d -
140 Johnathan Rd 255 Westwood Pl										127a 26
28. City State Zip 58. City State Zip										127b -
Manchester NJ 08759 Brick NJ 08724										127c -
30. Eyes DL Class Restrictions Endorsements 31. State 60. Eyes DL Class Restrictions Endorsements 61. State										127d -
05 - D - - - - - - NJ 020874										127e 22
32. Driver's License Number 33. DOB 34. Expires 62. Driver's License Number 63. DOB 64. Expires										128 22
Z4176 77600 07525 072452 0918 020874										129 02
35. Owner's First Name Initial Last Name 65. Owner's First Name Initial Last Name										130 02
☐ Same as Driver Patricia Ziemba ☐ Same as Driver										131 -
36. Number & Street 66. Number & Street										132 -
140 Johnathan Rd										133 02
37. City State Zip 67. City State Zip										134 -
Manchester NJ 08759										135 -
38. Make 39. Model 40. Color 41. Year 42. Plate No. 43. State 68. Make 69. Model 70. Color 71. Year 72. Plate No. 73. State										136 -
HON ACC BK 14 C11EJH NJ										137 02
44. VIN 45. Expires 74. VIN 75. Expires										138 -
1HGC R3F86EA028177 06/18										139 -
46. Vehicle Removed to: 76. Vehicle Removed to:										140 -
☒ Driven ☐ Towed Disabled ☐ Towed Disabled & Impounded ☐ Driven ☐ Towed Disabled ☐ Towed Disabled & Impounded										141 -
☐ Left at Scene ☐ Towed Impounded ☐ Left at Scene ☐ Towed Impounded										142 -
47. Authority 77. Authority										143 -
☐ Owner ☒ Driver ☐ Police ☐ Owner ☐ Driver ☐ Police										144 -
48. Alcohol Drug Test 49. Hazardous Material 78. Alcohol Drug Test 79. Hazardous Material										145 -
Given: ☐ No ☐ Yes ☐ Refused ☐ None ☐ On Board ☐ Spill Given: ☐ No ☐ Yes ☐ Refused ☐ None ☐ On Board ☐ Spill										146 -
Type: ☐ Breath ☐ Blood ☐ Urine Type: ☐ Breath ☐ Blood ☐ Urine										147 -
Results: 0 % ☐ Pending Hazard Class Placard No. Results: 0 % ☐ Pending Hazard Class Placard No.										148 -
50. Carrier No. 51. GVWR / GCWR (trucks & buses only) 80. Carrier No. 81. GVWR / GCWR (trucks & buses only)										149 -
☐ USDOT ☐ None ☐ ≤ 10,000 lbs. ☐ 10,001 - 26,000 lbs. ☐ ≥ 26,001 lbs. ☐ USDOT ☐ None ☐ ≤ 10,000 lbs. ☐ 10,001 - 26,000 lbs. ☐ ≥ 26,001 lbs.										150 -
52. Motor Carrier or Government Entity 82. Motor Carrier or Government Entity										151 -
Number & Street Number & Street										152 -
City State Zip City State Zip										153 -
135. Damage to Other Property ☐ Yes (If Yes, describe) ☒ No										154 -
Oper. 136. Charge 137. Summons No. Oper. 138. Charge 139. Summons No.										155 -
Oper. 140. Charge 141. Summons No. Oper. 142. Charge 143. Summons No.										156 -
83 84 85 86 87 88 89 90 91 92 93 94 95 Names & Addresses of Occupants If Deceased, Date & Time of Death										157 -
A V1 01 01 - 64 M - - - 11 04 - - Walter Ziemba, 140 Johnathan Rd, Manchester, NJ 08759										158 -
B V1 03 01 - 64 F - - - 11 04 - - Patrica Ziemba, 140 Johnathan Rd, Manchester, NJ 08759										159 -
C P1 - - 03 42 M 11 08 02 - - - 1506 Kevin Turiano, 255 Westwood Pl, Brick, NJ 08724										160 -
D										161 -

	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death
E														
F														
G														
H														
I														
J														

144. Crash Diagram



145. Crash Description/Narrative

Vehicle #01 was traveling south in the parking lot of Walmart, located at 1872 Route 88, and passing the north entrance/exit in front of the store. Pedestrian #01 exited Walmart's north exit and was crossing the roadway directly in front of the store, within the pedestrian crosswalk. Pedestrian #01 stated he did not see vehicle #01 approaching while he was walking across the roadway, at which time vehicle #01 struck pedestrian #01. Driver of vehicle #01 stated he had slowed earlier in the crosswalk for passing pedestrians and as he proceeded forward, pedestrian #01 came out of the "shadows" and entered the roadway in front of his vehicle. Driver of vehicle #01 also indicated there was a significant sun glare which made it hard to see pedestrian #01. Pedestrian #01's left side was struck by vehicle #01's passenger side front quarter panel. Pedestrian #01's left foot/ankle was also run over by vehicle #01's passenger side front tire.

Vehicle #01 was moved prior to police arrival. Pedestrian #01 had complaint of pain to his left ankle/foot. No other injuries were reported at the scene. Brick Police EMS arrived on location and transported pedestrian #01 to Ocean Medical Center.

Walmart had video surveillance of the accident which I viewed prior to leaving. I observed pedestrian #01 exit Walmart at the north exit, stand on the platform for a moment while looking into the parking lot, then proceeded forward into the crosswalk headed in a southeast direction. Vehicle #01 was observed slowing in the beginning of the crosswalk then proceeded forward towards pedestrian #01's location. Pedestrian #01 was a few feet within the crosswalk when vehicle #01 came from behind and struck pedestrian #01. The platform area outside the exit doors was observed as a shaded area which continues partially into the crosswalk, causing multiple shadows. Sun-glare was observed while traveling south through the crosswalk.


146. Officer's Signature 	147. Badge # 239	148. Reviewer 	Badge # 1128	149. Case Status ☐ Pending ☒ Complete
------------------------------	---------------------	-------------------	-----------------	---

New Jersey Police Crash Investigation Report


Police Dept: _____ Code: **01-Municipal Police**


Motor Vehicle Crash Diagram


Station: _____ Case No: **2017-00007496**



Walmart
1872 Route 88



 #239
Officer's Signature


Badge Number