

NJTR-1 (Rev. 01/17)


**New Jersey Police
Crash Investigation Report**

Case Number
1881-17

Page 2 of 3

	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death
E														
F														
G														
H														
I														
J														

144. Crash Diagram



145. Crash Description/Narrative

Vehicle 1 was marked Brick Police vehicle #197. Vehicle 1 was traveling on Route 70 east prior to the intersection with Route 88. Vehicle 1 was traveling in the right lane to continue east on Route 70. Vehicle 2 was on Route 70 east prior to the intersection with Route 88. Vehicle 2 was in the right turn lane to turn onto Route 88 east. Vehicle 1 attempted to change lanes into the right turn lane for Route 88 east and sideswiped Vehicle 2.

The driver of vehicle 1 stated he attempted to change lanes and did not see Vehicle 2, because the vehicle must have been in his blind spot.

I determined that the driver of vehicle 1 was at fault for this crash due to an improper lane change and driver inattention. There were no injuries reported on scene.

Vehicle 1 insurance information

Self Insured ID #05-87

Perma, Inc

9 Campus Drive

Parsippany, NJ 07054

146. Officer's Signature

NJTR-1 (Rev. 01/17)

147. Badge #

148. Reviewer

Badge #

149. Case Status


☐ Pending ☒ Complete

New Jersey Police Crash Investigation Report

Motor Vehicle Crash Diagram

Police Dept: _____ Code: 01-Municipal Police

Station: _____ Case No: 2017-00001881



[Signature]
Officer's Signature

210
Badge Number