

96	Page 1 of 3		☐ Fatal		New Jersey Police Crash Investigation Report										☒ Reportable		☐ Non-Reportable		☐ Change Report		118a							
05	1. Case Number				10. Crash Occurred On: 214 JACK MARTIN BLVD										11. Speed Limit		12. Route No.		13. Milepost		10							
97	2022-00010831				Road Name										Dir						118b							
01	2. Police Dept. of				Code		At Intersection with														02							
98	Brick Police				01		☐ Feet														119a							
01	3. Station/Precinct						☐ Miles														25							
99	4. Date of Crash				5. Day of Week		6. Time		7. Municipality		8. Total Killed		9. Total Injured		19. To: 17. Cross Road Name/Route No.		18. Speed Limit		119b									
09	mm dd yy				Su M Tu W		(use 2400 hrs.)		Code						Ramp From: -		NB EB SB WB		—									
100a	0 2 1 0 2 2				F Sa		1 1 5 1		1 5 0 6		-		-		21. Latitude		22. Longitude		120a									
01																			00									
100b	23. Veh. #				24. Policy No.		25. NJ Ins. Code		53. Veh. #		54. Policy No.		55. NJ Ins. Code						120b									
04	01								02		004ISAH25559630		004						—									
101	☐ Parked ☐ Ped ☐ Pedalcyclist ☐ Resp. to Emergency ☐ Hit & Run								☐ Parked ☐ Ped ☐ Pedalcyclist ☐ Resp. to Emergency ☐ Hit & Run										121a									
02	26. Driver's First Name				Initial		Last Name		29. Sex		56. Driver's First Name		Initial		Last Name		59. Sex		01									
102							HIT AND RUN		00										121b									
103	27. Number & Street										57. Number & Street								—									
01																			—									
104	28. City				State		Zip				58. City		State		Zip				—									
02																			—									
	30. Eyes				DL Class		Restrictions		Endorsements		31. State		60. Eyes		DL Class		Restrictions		122									
	-				-		-		-		-		-		-		-		13									
105	32. Driver's License Number				33. DOB		34. Expires		62. Driver's License Number		63. DOB		64. Expires						10									
06					mm dd yy		mm yy				mm dd yy		mm yy						—									
																			—									
106	35. Owner's First Name				Initial		Last Name		65. Owner's First Name		Initial		Last Name						124									
	☐ Same as Driver								☐ Same as Driver				LABORTORY CORP OF AMERICA						11									
107	36. Number & Street								66. Number & Street										125									
									69 FIRST AVE										11									
108	37. City				State		Zip		67. City		State		Zip						126a									
00									RARITAN		NJ		08829						28									
109	38. Make		39. Model		40. Color		41. Year		42. Plate No.		43. State		68. Make		69. Model		70. Color		126b									
04													Chevrolet		Equinox		SL		—									
110	44. VIN				45. Expires				74. VIN				75. Expires						126c									
00									2 G N A X J E V 7 L 6 1 9 5 2 8 4				12/22						—									
111	46. Vehicle Removed to:								76. Vehicle Removed to:										126d									
02																			—									
112	☒ Driven ☐ Towed Disabled ☐ Towed Disabled & Impounded								☐ Driven ☐ Towed Disabled ☐ Towed Disabled & Impounded										126e									
00	☐ Left at Scene ☐ Towed Impounded								☒ Left at Scene ☐ Towed Impounded										28									
113	47. Authority								77. Authority										127a									
	☐ Owner ☒ Driver ☐ Police								☒ Owner ☐ Driver ☐ Police										26									
114	48. Alcohol Drug Test				49. Hazardous Material				78. Alcohol Drug Test				79. Hazardous Material						127b									
	Given: ☒ No ☐ Yes ☐ Refused				☒ None ☐ On Board ☐ Spill				Given: ☒ No ☐ Yes ☐ Refused				☒ None ☐ On Board ☐ Spill						—									
115	Type: ☐ Breath ☐ Blood ☐ Urine								Type: ☐ Breath ☐ Blood ☐ Urine										127c									
	Results: 0. - % ☐ Pending				Hazard Class		Placard No.		Results: 0. - % ☐ Pending				Hazard Class		Placard No.				—									
116																			127d									
	50. Carrier No.				51. GVWR / GCWR (trucks & buses only)				80. Carrier No.				81. GVWR / GCWR (trucks & buses only)						127e									
	☐ USDOT ☒ None				☐ ≤ 10,000 lbs. ☐ 10,001 - 26,000 lbs. ☐ ≥ 26,001 lbs.				☐ USDOT ☒ None				☐ ≤ 10,000 lbs. ☐ 10,001 - 26,000 lbs. ☐ ≥ 26,001 lbs.						26									
01																			—									
	52. Motor Carrier or Government Entity								82. Motor Carrier or Government Entity										128									
																			28									
	Number & Street								Number & Street										129									
																			06									
	City				State		Zip		City				State		Zip				130									
																			06									
	135. Damage to Other Property				☐ Yes (If Yes, describe) ☒ No														131									
																			11									
																			11									
	Oper.				136. Charge		137. Summons No.		Oper.				138. Charge		139. Summons No.				133									
																			00									
	Oper.				140. Charge		141. Summons No.		Oper.				142. Charge		143. Summons No.				134									
																			03									
	Names & Addresses of Occupants														If Deceased, Date & Time of Death													
A	83	84	85	86	87	88	89	90	91	92	93	94	95	HIT AND RUN														
	01	01	01	00	—	00	00	00	—	00	00	00	—															
B																												
C																												
D																												

New Jersey Police Crash Investigation Report												Case Number 2022-00010831			Page 2 of 3	
E F G H I J	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death		

144. Crash Diagram

Show NORTH by Arrow
(Not to Scale)

SEE ATTACHED DIAGRAM

145. Crash Description/Narrative

Vehicle #1 collided with Vehicle #2 while backing out of a parking space in the parking lot of 214 Jack Martin Boulevard near building D Unit 3 (Lab Corp). Vehicle #1 fled the scene and Vehicle #2 was parked and unoccupied.

On arrival I spoke to a representative of Lab Corp who advised he arrived at the above location at approximately 0800 hours and did not observe any damage to Vehicle #2. However at 1130 hours a fellow employee reported observing front end damage on Vehicle #2. I observed Vehicle #2 which was parked in a legal parking space and had front drivers side damage. Based on the damage it appears Vehicle #1 backed into Vehicle #2 while backing out of a parking space. I checked the parking lot for any vehicles that may have been involved but had negative results. I also checked the area for possible video surveillance which yielded negative results. There is information on the suspect vehicle (Vehicle #1) at this time.



146. Officer's Signature Frank James Giambona	147. Badge # 290	148. Reviewer John D Gordon	Badge # 237	149. Case Status ☐ Pending ☒ Complete
--	---------------------	--------------------------------	----------------	---

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram

Police Dept: Brick Police Code: 01
Station: Case No: 2022-00010831

144 Crash Diagram (NOT TO SCALE)

○ Indicate
North



214 JACK MARTIN BLVD BUILDING D

Frank James Giambona

Officer's Signature

290

Badge Number