

NJ Accident Report 2016-00080980 Page 1 OF 3

New Jersey Police Crash Investigation Report

Motor Vehicle Crash Description

Police Dept: _____ Code: **01-Municipal Police**Station: **Brick Police** Case No: **2016-00080980**

(Refer to vehicle by number)

	Veh Occ	Pos In/On	Eject	Phys Cond	Age	Sex	Loc Inj	Type Inj	Ref Med	Equip Avail	Equip Used	Bag Depl	Hosp Code	Names & Addresses of Occupants - If Deceased, Date & Time of Death
ALL INVOLVED	83	84	85	86	87	88	89	90	91	92	93	94	95	
	A													
	B													
	C													
	D													
E														

135 Crash Description

On 12/19/16 at 1302 hours I was dispatched to the area of Rt. 70 and Van Zile Rd in reference to a two car motor vehicle accident. Upon arrival I observed both vehicles pulled off on to the shoulder of Rt. 70 eastbound just east of Van Zile Rd.

Driver 1 advised he and vehicle 2 were traveling east bound in the left lane of travel on Rt. 70. As he was driving in front of vehicle 2 he noticed vehicle 2 driving extremely close to his vehicles rear. Vehicle 1 changed into the right lane to allow him to pass at which point vehicle accelerated at a high rate of speed to pass him. After vehicle 2 passed he changed back into the left lane and was now behind vehicle 2. Vehicle 2 suddenly applied his brakes unnecessarily thirty feet prior to the traffic signal at Van Zile Rd with no other vehicles in front of him causing vehicle 1 to crash into him.

Driver 2 advised he and vehicle 1 were traveling east bound in the left lane of travel on Rt. 70. As he was driving behind vehicle 1 it changed to the right lane of travel. After vehicle 1 was done changing lanes driver 2 proceeded to drive past him. As driver 2 approached the red traffic signal of Van Zile Rd he observed vehicle switch back into the left lane directly behind him. Vehicle 2 had to apply his brakes as to not drive through a red traffic signal, but due to how close vehicle 1 was to the rear of his vehicle it caused vehicle 1 to crash into him.

Investigation revealed vehicle 1 and 2 were both traveling east bound in the left lane of travel on Rt 70 as they approached the intersection of Van Zile Rd. Vehicle 2 stopped prior to the intersection and vehicle 1's front crashed into the rear of vehicle's 2 rear causing damage to both vehicles. There was no debris or marks in the roadway to definitively identify the location of the crash. There were no reported injuries at this time.

New Jersey Police Crash Investigation Report

Motor Vehicle Crash Diagram

Police Dept: _____ Code: 01-Municipal Police

Station: Brick Police

Case No: 2016-00080980

