

NJ Accident Report 2016-00074094 Page 1 OF 3

New Jersey Police Crash Investigation Report

Police Dept: _____ Code: **01-Municipal Police**

Motor Vehicle Crash Description

Station: **Brick Police**Case No: **2016-00074094**

(Refer to vehicle by number)

	Veh Occ	Pos In/On	Eject	Phys Cond	Age	Sex	Loc Inj	Type Inj	Ref Med	Equip Avail	Equip Used	Bag Depl	Hosp Code	Names & Addresses of Occupants - If Deceased, Date & Time of Death
A	83	84	85	86	87	88	89	90	91	92	93	94	95	
B														
C														
D														
E														

135 Crash Description

Vehicle #1 was in the left lane traveling North on Jack Martin Blvd. Vehicle #2 was in the right lane traveling in the same direction while slowing to make a right turn in traffic onto Burrsville Road. Driver #1 suddenly attempted to change lanes and struck Vehicle #2 on the driver side with the front right fender of Vehicle #1.

Driver #2 advised that she was behind a vehicle and both were slowing down to make a right turn at the green light. Driver #2 stated Vehicle #1 suddenly turned into and struck the driver side of Vehicle #2. Driver #1 stated she was in the left turn lane and vehicles in front of her were stopping to make the left turn. Driver #1 advised that she attempted to change lanes to go straight and thought she had enough room but advised that Vehicle #2 must have been speeding.

The damage to both vehicles was mainly scratching and paint transfer, and was consistent with that of slow moving vehicles. Based upon my observations, and statements made by both drivers, I find Driver #1 at fault for improper lane change and failure to yield the right of way to vehicle #2. Driver #1 was issued traffic summons E16 07165 for 39:4-97a(Careless Driving).

New Jersey Police Crash Investigation Report

Motor Vehicle Crash Diagram

Police Dept: _____ Code: **01-Municipal Police**

Station: **Brick Police**

Case No: **2016-00074094**

