

NJTR-1 (Rev. 01/17)

New Jersey Police Crash Investigation Report												Case Number 2022-00018689			Page 2 of 3	
	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants <i>If Deceased, Date & Time of Death</i>		
E																
F																
G																
H																
I																
J																

144. Crash Diagram



Show NORTH by Arrow
(Not to Scale)

SEE ATTACHED DIAGRAM

145. Crash Description/Narrative

Vehicle #1 was traveling north on Jack Martin Boulevard and struck a curb in the area of Albert Cucci Drive.

Vehicle #1 was disabled and located by patrols stopped in the shoulder of Jack Martin Boulevard with both passenger side wheels blown out.

Vehicle #1 operator stated she drove off the side of Jack Martin Boulevard and struck the curb, causing both tires to blow out. Vehicle #1 operator stated she took her eyes off the road because she was removing her false tooth while driving.

No injuries were reported. Vehicle #1 suffered two flat tires and damage to both alloy wheel rims. Vehicle #1 was moved into a parking lot and was later removed by a private tow. No damage was observed to the area of impact.

146. Officer's Signature Evan Charles Mancini	147. Badge # 282	148. Reviewer John C Boronkas	Badge # 165	149. Case Status ☐ Pending ☒ Complete
--	---------------------	----------------------------------	----------------	---

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram

Police Dept: Brick Police


Code: 01

Station:

Case No: 2022-00018689


144 Crash Diagram (NOT TO SCALE)

Indicate
North



Not To Scale

Jack Martin Blvd.



Evan Charles Mancini

Officer's Signature

282

Badge Number