

NJTR-1 (Rev. 01/17)

NJTR-1 (Rev. 01/17)


**New Jersey Police
Crash Investigation Report**

Case Number
2022-00021626

Page 3 of 4

	83	84	85	86	87	88	89	90	91	92	93	94	95	Names & Addresses of Occupants If Deceased, Date & Time of Death
E														
F														
G														
H														
I														
J														

144. Crash Diagram



Show NORTH by Arrow
(Not to Scale)

SEE ATTACHED DIAGRAM

145. Crash Description/Narrative

Vehicle 1 was traveling east bound on Route 88 approaching the intersection with Midstreams Rd. At that time,

Vehicle 1 ran off the roadway to the right and struck a circular landscape planter made of bricks.

Simultaneously, Vehicle 1 also struck a "No Turn on Red" sign causing it to fall down. Vehicle 1 then fled the scene.

Vehicle 1 sustained unknown damage and at the time of this report, has not been identified. There were no witnesses to this crash. A check of the surrounding area for Vehicle 1 yielded negative results.

My body worn camera was activated for this incident.

146. Officer's Signature
Scott Edward Mesmer

147. Badge #
292

148. Reviewer
Thomas P Caulfield

Badge #
235

149. Case Status
☒ Pending ☐ Complete

New Jersey Police Crash Investigation Report
Motor Vehicle Crash Diagram


Police Dept: Brick Police

Code: 01

Station:

Case No: 2022-00021626

144 Crash Diagram (NOT TO SCALE)



Scott Edward Mesmer

292